

MAY 28 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Chippewa County Remonumentation Corner #7.00 LAND CORNER

For corners in

| Chippewa County | Located in: | Corner Code # |
|------------------------------------|-------------|---------------|
| 1. Public Land Survey | T46N R1E | K-12 |
| | T R | |
| | T R | |
| | T R | |
| 2. Property Controlling in Section | S T R | |
| | S T R | |
| 3. Miscellaneous Property in Sec. | S T R | |
| | S T R | |
| 4. Lot No. , Recorded Plat | | |
| 5. Private Claims | | |

#2.00 HSSR
 2/28/1997 2:56:57 PM Receipt #217
 RECEIVED FOR RECORD
 CHIPPEWA COUNTY - STATE OF MICHIGAN
 SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK 9 PAGE 357

Register of Deeds Stamp & File Number

I, William L. Karr, in a field survey on November 28, 1996, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(K-12) 1/4 Corner Common to Sections 35 & 36, T. 46 N., R. 1 E.

1845 J.H. Mullett set post in original survey.

1909 F.H. Brown in field book in County Surveyors Office states that Carleton had set section corners by dividing up the three miles from the NW corner of section 24, South to the township line. The notes show no evidence of 1/4 corners on this line.

1910 F.H. Brown in field notes in County Surveyors Office, show 2665' on the South 1/2 mile on the West side of section 36.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(K-12) 1/4 Corner Common to Sections 35 & 36, T. 46 N., R. 1 E.

This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

Found 1/2" iron 3' West of centerline North-South gravel road. Position falls within 0.5' of being mid-way and on-line between the section corners to the North and South.

Accepted corner as found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(K-12) 1/4 Corner Common to Sections 35 & 36, T. 46 N., R. 1 E.

Corner is a 1/2" iron 3' West of centerline Lower Haylake Road.

| | | | |
|------------|----------------|---------|--------|
| Witnesses: | 8" Spruce | N 82° E | 35.58' |
| | 22" White Pine | S 39° E | 44.58' |
| | 11" Jack Pine | S 64° W | 35.26' |
| | 16" Jack Pine | N 41° W | 43.66' |

Bearings are compass bearings, corrected for declination, all distances are to a nail and tag in the side of the witness object unless otherwise noted.

Signed by William L. Karr

Date 12-30-96

Surveyor's Michigan License No. 27450

