

MAY 28 1997 CHIPPEWA COUNTY REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFIC Filing Requirement of Act 74, Mich. P.A. 1	
For corners in Chippewa Located In: Corner Code #	\$7.00 RECORDING FEE
Chippewa Located In: Corner Code #	\$2.00 MSSR
1. Public Land Survey	3/3/1997 5:11:29 PM Receipt #275 RECEIVED FOR RECORD
2. Property Controlling ST_R	CHIPPEVA COUNTY - STATE OF MICHIGAN SHARON H. KENNEDY, REGISTER OF DEEDS
in Section S T R 3. Miscellaneous S T R Property in Sec. S T R	BOOK 10 PAGE 28
	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	ABCDEFGHIJKIM
	2 6 5 4 3 2 1 1
, Keith R. Waters 12/16 96	3
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in	
conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or	5 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7
that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented	
recovered, found as expressed below:	8 19 20 21 22 23 24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded	9
on this certificate.	10 30 29 28 27 26 25
	11 32 33 34 35 36
	12 31 33 30 30 30 30 30 30 30 30 30 30 30 30
A. Description of original monument and accessories and/or subsequent restoration:	
 H-5 1/4 Corner Common to Sections 10 & 15, Town 46 North, Range 1 West 1845 - Original corner (James Mullett) was a 10" Maple. Circa 1900 - County Surveyor Frederick H. Brown notes indicate "this 1/4 post was gone an His drawing indicates corner midway between original section corners 2436 feet east 	and west.
	E 1/1/46
	orner:
B. Description of corner evidence found and/or method applied in restoring or reestablishing co	orner:
This corner is being re-established as part of the Chippewa County Remonumentation Program. Found no evidence of corner. Re-established corner on line between section corners 2438.41 feet east and 2430.03 feet west, on the extension of a very old fence line to the north. I believe that the fence location is most likely based on Brown's corner location. Corner falls in the approximate centerline of an east-west 2 track road (8 Mile Road).	
* *	
	STATE OF MICHIE
C. Description of monument for corner and accessories established to perpetuate locating the p	osition of the corner: KEITH R. WATERS
Corner is a ¾" x 24" rebar with a plastic Chippewa County Remonumentation cap in the approf east-west 2 track road (8 Mile Road). Witnesses: 9" Spruce, \$23°E 223.82'	osition of the corner: WATERS PROFESSIONAL SURVEYOR No. 3 3 1 1 2
5" Twin Spruce, S14°E 202.25'	A 33143
3" Spruce, N83°W 64.28' Corner Fence Post, N04°E 30.39'	Who was the state of the state
Note: Unless noted otherwise, distances are to a nail/tag #33142 in the side of the witness o corrected for declination. Trees are blazed and painted.	bject. Bearings are compass bearings
Signed by Keith R. Water Date	2-30-96
Surveyor's Michigan License No. 33142	2-30-96 BOOK 10 PAGE 28
	BOOK 10 PAGE 28