## 194A R 2.77 1996 CHIPPEWA COUNTY REMONUMENTATION CORNER

WAR O I 1000	LAND	CORNER RECOR	DATION CERTIF	FICATE					
For corners in	Filing	g Requirement of A		. 1970\$ 7.:		CORNER		4.	
Chippewa 1				I	00 MSSR B 96 9::	54 A.M.	ii. Rece	· Elpth (	<b>37</b>
(County)	_ocated in:	Corner Code #			RECE	IVED FOR	RECORD		
	<b>77</b> 7NI <b>23</b> 1	1W C-12			PEWA COU ON H. KEI				
1. Public Land Survey	T47N R.1 T R_ T R_	TW C-12		<u> </u>	un ita ali	AACDIS VE	.0161CR	UF ME	era era
2. Property Controlling Sin Section	3 TR_ 6 TR_		<del></del>						
3. Miscellaneous	TR		· · ·						
Property in Sec.	S TR_		<del></del>	Re	egister of	Deeds S	tamp &	File Nu	ımber
			J	L	<u> </u>				
4. Lot No, Recorded				А	B C D	E F	G H :	ΙJ	K L :
5. Private Claims			<del></del>	1	ĬĬĬĨ	ĪĪ			
				2	5	1 1	3	2-  1	† †
Keith R. Waters		12/09 495	o hereby state that un	3					
i,, in requirements of P.A. 74, Michigan P.	a field survey on _ A. of 1970, the corne	, 19 do	o hereby state that und s 1 and 2 above were	in ĺ	1   8	- J	10-	1 1	12
conformance with regulations and rule. United States Department of the Interior	s therefore as required	d in the current manual of s	survey instructions of t	the <sup>5</sup>	10 17	16	1 =		13
that the corner points mentioned in lin	nes 3, 4 and 5 above v	were in conformance with t	the rules of the Michig	gan ˌ	18 17		15		
Board of Land Surveyors or by a Drecovered, found as expressed below:		f Law; established, re-es	tablished, monument	ed, ′	1920	21_		23_	24-
				9					
NOTE: Not more than 2 corners, on this certificate.	all in the same towr	n and range, may be rec	oraea	10	3029	28	27	  26	25-
on and octahodic.				11	1			<u> </u>	-
				12	31-4-32	33	34	35	36-
				13				<u> </u>	
C-12 1/4 Corner Common to Sec 1845 - Original ties (James Mull 1973 - Unrecorded LCRC by un- clearing. Witnesses: 14" 1977 - Recorded plat of "Sault V 1987 - Earl S. Strater, P.S. 2842 14" Yellow Birch, N62°E (Witnesses are nails with	ett): Birch 12, S8 known surveyor in Yellow Birch, No West", Wayne Bos: 4, unrecorded LCI E 30.03' - 12" Map	32°E 09 links - Birch 1 ndicates a concrete mo 61°30'E 29.9' - 12" M ss, R.L.S. 20703, show RC. Found 4" concret	0, S43°W 08 links nument with a bra aple, S48°E 7.5' - s corner at a distar e monument. With	ss cap in a 8" Maple, ace of 2633 nesses:	S60°W 1	9.3' - 3"	Balsam,	, N17°	W 5.5'
B. Description of corner evidence	ce found and/or me	ethod applied in restorir	ng or reestablishing	corner:					
This corner is being perpetuated Found an old 4" concrete monum the Sault West plat. Distances to Section 32. Accepted corner as	nent and three bear Section corners r	ring trees as called for	in 1987 unrecord	ed LCRC n					th
						4	55555X	F MIC	Marie Contract
C. Description of monument for	corner and access	ories established to per	petuate locating the	e position of	f the corn	er:	KE	ITH R.	CAN
Corner is an old 4" concrete mor			iller.	A CHARLES CONTRACTOR OF THE CO	Willer.	# £	• • • • • • • • • • • • • • • • • • • •	ATERS	
Witnesses:	ranione with a lout	ndod, weathered top.	S. T. Hilling	SARS.	E.M.	8*		AND RVEYOR	
10" Yellow Birch, N61°W 18.62				( 1 / S	外省	WE	<b>v</b> .	No. 3142	0,0
14" Yellow Birch, N63°E 30.00 12" Red Maple, S42°E 7.44' (Na				12/8/98	5 ( ) 6 原	De	VSED.	******	ME
12" Red Maple, \$63°W 19.82' (				wer			MA	AND	3355
Note: Trees are blazed and pain	ted		The transfer of the second	WIDMAN	Charling.			•	
Bearings are compass be		or declination.		Annual desirence of the control of t	apr.			•	
			<b>.</b> .		0.0	1005			
Signed by KITCH			Date	Decemb	er 29.	1995			

Surveyor's Michigan License No. 33142