MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_48_ NR__6 N__

		Chippewa	COUNTY
DESCRIPTION OF CORNE	R 1/4 Section Corner between Sections 5 and 6		
DESCRIPTION OF CORNER	MONUMENT_	1" pipe with 4" by	ras_cap
WITNESSES TO CORNER	12" CedaR	S_16°_E	142 links
	9" Cedar	s 78° w	19½ links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 Corner from two Cedar B.T.'s in good condition.

Corner lies in Cedar swamp.

Corner found by Forestry Division Survey Crew while making a partial re-survey in this area 1954.

Corner placed and witnessed June 20, 1956.

SURVEYORS SEAL

SIGNED SILLY BUCKLES DATE 6/21/56