## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T\_48 NR 6 W

		CulppewsCOUNTY
DESCRIPTION OF	CORNER _	Section Corner common to Sections 7,8,17,18
DESCRIPTION OF	CORNER M	ONUMENT_1*_Pipe_with_4* Brass-cap
WITTNESSES TO	CORNER _	_2°_4. Pine = 8 36 N = 72_Links
		_9"_J_ Pine = N 78 F_~ 73 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This cernor was established, by proportionate measurement, by Forestry Division survey crew, while making a partial resurvey of this area. Good Meander Cernor 8 chs. South.

Corner was placed and witnessed May 11, 1954.

SURVEYORS SEAL

SIGNED LAND SURVEYOR DATE 2/25/55