

✓

**MICHIGAN**  
**DEPARTMENT OF CONSERVATION**  
**FORESTRY DIVISION**

**LAND CORNER RECORD**

T. 49... NR. 6-7 W..

----- ~~Chippewa~~ *Chippewa* ----- COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sec.'s 7-12 -----

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap -----

WITNESSES TO CORNER 7" Jack Pine ----- N 40° W ----- 132 links

"1/4 S NBT"

8" Red Pine ----- S 86° E ----- 172 links

"1/4 S NBT"

**DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.**

Replaced 1/4 corner from two B.T.'s.  
One tamarack bearing N 27° W, 28 links, B.T. in good condition.  
One spruce stump bottom marked with wood slab. bearing S 28° W, 39 links.

Found iron pipe set by Marcus Schaff, Reg. Surveyor.

1/4 corner lies 1/2 chain South of road.

Shown to us by J. Kutchera, Ass't District Forester.

Corner placed and witnessed December 6, 1957.

**SURVEYORS SEAL**

SIGNED *Billy D. Buckles* DATE 12/19/57  
REGISTERED LAND SURVEYOR