

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49N N.R. 6W


Chippewa COUNTY

DESCRIPTION OF CORNER 1/4 corner on north side, Sec. 5, on the 5th correction line

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 6-16-69

WITNESSES TO CORNER..... 9" jack pine (1/4 S 5 BT) S33°E 11.8'



7" jack pine (1/4 S 5 BT) S81°W 4.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed midway between the closing corners, 1/2 mile to east and west, and on the 5th correction line.

Note: This 1/4 corner was not placed in the original survey.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler DATE 8-29-69
REGISTERED LAND SURVEYOR