

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49N N. R. 6W


Chippewa COUNTY

DESCRIPTION OF CORNER Closing corner bet. Secs. 4-5, on the 5th correction line

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 6-16-69

WITNESSES TO CORNER..... 8" jack pine (S4 NBT) S18°E 22.4'



8" jack pine (S5 NBT) S58°W 14.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established on line with Sec. Cor. to west and Sec. Cor. 6.91 chs. to east. Found numerous pine stumps in vicinity but no evidence of the original witnesses.

Corner lies 42' south of an old E-W R.R. grade.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler DATE 8-29-69
REGISTERED LAND SURVEYOR