

# LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Chippewa Co.

3 Corners.

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____ T. _____	N. S., R. _____ E. W.	9-Sec.30, 13-Sec.30
2. PROPERTY CONTROLLING IN SECTION <u>30</u> , T. <u>49</u>	N. S., R. <u>6</u> E. W.	14-Sec.30
3. MISCELLANEOUS PROPERTY IN SECTION _____ , T. _____	N. S., R. _____ E. W.	
4. LOT NO. _____ , RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 6-12, 1981, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- 9-Sec.30 East 1/16 Corner, Section 30, T49N R6W.  
 13-Sec.30 South-East 1/16 Corner, Section 30.  
 14-Sec.30 South 1/16 Corner on East side of Section 30.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- 9-Sec.30 Found 1" Iron Pipe at corner.  
 13-Sec.30 Found 1" Iron Pipe at corner.  
 14-Sec.30 Found 1" Iron Pipe in place.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Re-witnessed 1" pipes. Bearings:

- 9-Sec.30 None available.  
 13-Sec.30 6" J. Pine, N78°E, 33.0' & 5" J. Pine, S48°E, 48.4'.  
 14-Sec.30 4" Spruce, South, 16.8' & 4" Spruce, East, 7.2'.

SIGNED BY

*Billy D. Buckler*

DATE 7-15-81

Billy D. Buckler  
 SURVEYOR'S MICHIGAN REGISTRATION NO. 8887

