LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Chippewa Co.

2 Corners.

	•···- p	P 0.0 100	2 001110101	
FOR C	CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
I. PU	BLIC LAND SURVEY	T.49 *., R. 6 *	. н-3	
2. PR	OPERTY CONTROLL- ING IN SECTION—	10 ,T. 49 N. R. 6 W	2-Sec.10	
		, T	ľ	
4. LO	T NO , RI	ECORDED PLAT		•
5. PRI	IVATE CLAIMS REGISTER OF DEEDS STAMP AND FILING NUMBER			
I	Billy D. Buc	kler do hereby	certify that under requirements	of P.A. 74, Michigan P.A. of 1970,
Burea and 5 as exp	u of Land Management above were, in a field st	or by a decree of a court of lav	w. Furthermore, that the corne ,, 19, found, recovered, re-	States Department of the Interior, or points mentioned in lines 3, 4 stored, established or re-established tration for Land Surveyors or, by a
A. D	escription of original mo	nument and accessories and/or	subsequent restoration:	
·3	1/4 Cor. bet. Sec's. 3-10, set by Wells Burt, D.S. in 1849. Bearings were: W. Birch 4", West, 2.29 chs. and Y. Birch 8", East, 8.55 Chs.			
- 5e c.10	East 1/16 corner	r on North side of Sec	etion 10.	
	;		•	
			olied in restoring or re-establishi	
·3	Re-established corner or eviden		ection corners. For	and no evidence of original
-Se c.10	Established com	mer midway bet. Sec. (Gor. to Bast and 1/4 Go	orner to West.
	• "	for corner and accessories estal	blished to perpetuate locating the	e position of the corner:
-3	New Bearings:	6" Cedar, NI ^O W, 21.3	3' and 6" Ceder, S73°	3, 5.9¹.
-Se c.10	Bearings: 4" Co	dar, N56 ⁰ E, 32.0' &	6 6 Cedar, N26 E, 16	5.0 & 6" Spruce, N84°W, 10
	A.Y.	V. D. Buch	<i>U</i> 2	BILLY DE BUCKLER

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887