Cons. 4047 4/88

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T.49. NR.7.W...

	Chippewa COUNTY
DESCRIPTION OF CORNER	1/4 corner between Sections 13 and 14.
DESCRIPTION OF CORNER	MONUMENT_1" Pipe with 4" Brass Cap
WITNESSES TO CORNER	18" Red Pine _ S 51 E, 23 Links _ (1/4 S. NBT) _
	5" Jack Pine S 59 W 19 Links (1/4 S MT)

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced as set by Harcus Schaaf, Reg. Surveyor. Found 2^n Iron Pipe in place with wood slabs at site of D.T. stumps.

Corner lies in old logging road.

Corner was placed and witnessed with J. Kutchera, Assistant, and L. Rubick, Aide, on 23 June 1958.

SURVEYORS SEAL

Billy D. Buckler

DATE 5-32-59 _

REGISTERED LAND SURVEYOR