

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49. NR. 7 W.

Chippewa COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 13, 14, 23 and 24.

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap.

WITNESSES TO CORNER 5" Cedar S ³ 54 W 16 Links, Marked "S 23 MBT"

8" Cedar S 68 E 32 Links, Marked "S 24 MBT"

6" Cedar N 20 E 78 Links, Marked "S 13 MBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced as set by Marcus Schaaf, Reg. Surveyor.

Found iron pipe and woodpost in place. Found Cedar B.T. bearing S 54 W, 51 Links.

The tree green and in good condition.

Corner shown to us by J. Kutchera, Assistant, and L. Rubick, Aide.

Corner was placed and witnessed on 5 February 1958.

SURVEYORS SEAL

SIGNED Billy D. Buchler
Billy D. Buchler DATE 5-19-59
REGISTERED LAND SURVEYOR