


STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

Chippewa COUNTY  
T 49N R 7E

DESCRIPTION OF CORNER 1/4 Corner bet. Secs. 28-33  
CORNER MONUMENT 2" Iron Pipe with 4" Brass Cap "Dept. of Conservation - State  
Park Survey"  
DATE MONUMENT PLACED AND WITNESSED 8-30-71  
WITNESSES TO CORNER..... 9" Jack Pine (1/2 NBT) S 16°W 57.4'



7" Jack Pine (1/2 S NBT) S39°E 47.1'  
AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-witnessed as set by State Park Survey 1939. Found a 4" concrete monument with 1/2" Iron Bar, beside the pipe. Found remains of a Jack pine bearing tree; a stump with bottom face and notch, S47°E, 37 links. Corner lies on north edge of a power line clearing and 14.8' north of the pole line.

SURVEYOR'S SEAL

SIGNED

*Billy D. Buckler*  
Billy D. Buckler

DATE

9-22-71

REGISTERED LAND SURVEYOR

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing ✓

R 4047  
Rev. 10/68