

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 50N N.R. 6W


Chippewa COUNTY

DESCRIPTION OF CORNER $\frac{1}{4}$ corner on south side, Sec. 32

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 6-16-69

WITNESSES TO CORNER..... 9" Red Pine ($\frac{1}{4}$ S 32 NBT) 27.4'



7" Red Pine ($\frac{1}{4}$ S 32 NBT) N62°E 46.9'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced from one pine stump, bearing N11E 17 lks. Found bottom of blaze and notch on stump.

Found what was apparently an old witness, effaced about 45' northwest of corner location.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler DATE 8-29-69
REGISTERED LAND SURVEYOR