

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 50N N. R. 6W


Chippewa COUNTY

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 32-33, on the 5th correction line

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 6-13-69

WITNESSES TO CORNER..... 7" Jack Pine (S32 NBT) north 34.3'



9" Jack Pine (S33 NBT) N74°E 22.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced from one original witness, a jack pine, bearing, N54°W, 43 links; tree down and badly rotted. Found evidence of face and partial scribe marks.

Corner lies on south slope and near top of a jack pine ridge.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler  
Billy D. Buckler  
REGISTERED LAND SURVEYOR

DATE 8-29-69