LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970 Chippewa Co.

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY		G-2A	
2. PROPERTY CONTROLL-	N. E. W. S., R. W.		
3. MISCELLANEOUS PROPERTY IN SECTION.	N. E. W. W. W.		
4. LOT NO , REC			
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND
			FILING NUMBER
I. Billy D. Buckler , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 8-4 , 1975, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on			
A. Description of original monument and accessaries and access			
Meander Corner set by Wells Burt, D.S. in 1849. Bearings were: W. Birch 7", S20½ W, 205 lks. and W. Birch 5", S48 E, 227 lks.			
G-2A Placed Witness	eroded considerable he meander corner.		nal corners 2.3 miles South. 247.1' South of record of a high sandbank and 90'
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:			
G_2A Set 1" pipe with 4" aluminium cap at Witness Corner.			
Bearings are:	16" W. Pine, N34 ^o k 14" R. Pine, S75 ^o E	29.2', and 16" W. :	Pine, S37°N, 35.2' and BILLY D
NOTE: Se	ee sketch on reverse	side.	G BUCKLER (S)
Sil	ly O. Buckler	DATE 8-25	NO.
SURVEYOR'S MICHIGAN	REGISTRATION NO. 88	87	(SEAL)
FOR STATE AND UNITE			
SIGNED BY	CHIEF OF SURVEY PARTY	DATE	
APPROVED AND SIGNED	BYMICHIGAN REGISTER	DATE	(GEAL)
	REGISTRATION NO		TO LID OF REGISTRATION, JAN. 28, 1971