CONS. 4047 4/56

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T 50 NR 7 7

	COUNT
DESCRIPTION OF CORNER	Section corner common to Sections 23, 24, 25 and 26.
DESCRIPTION OF CORNER	MONUMENT_1" Fipe with 4" Drags Cap.
WITNESSES TO CORNER	7" Jack Pine \$ 37 E 34 Links _ (3 25 ITT)
	7" Jack Pine _ S 60 M _ 29 Idnts _ (3 26 FOT)
	6" Jack Pine _ 1 18 E _ 33 Iidds _ (9 24 IBT)

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from two Jack Pine B.T.'s bearing 1 50 J, 13 Links. Tree down, poor condition, and strop bottom bearing S 59 E, 49 Links. Pine slabs at site of B.T.'s.

1" Iron Pipe with woodpost in place.

Corner lies 11 chains Sorth of woods road.

Location poster on road.

Corner was placed and witnessed with . Mutchera, As istant and L. Rubick, Aide, on 25 June 1958.

SURVEYORS SEAL

SIGNED BILLE D. Buckler DATE 5-20-59