

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T 50 .. NR .. 7 .. W

Chippewa COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 10, 11, 14, 15

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 13" Cedar (S 11 NBT) N 30° E 42 Links

9" Cedar (S 10 NBT) N 14° W 18 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from one Cedar (green) bearing N 59° W, 17 links. Chopped out scribe marks in excellent condition. Corner found by L. Rubick, Aide. Found Iron Pipe set by Combine Locks. Corner lies in north edge of swamp and at foot of a steep hill.

Corner was placed and witnessed September 1, 1960 with R. Norkali, D. F. and L. Rubick.

SURVEYORS SEAL

SIGNED

*Billy D. Buckler*  
REGISTERED LAND SURVEYOR  
Billy D. Buckler

DATE 9/15/60