

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 50. NR. 7. W

Chippewa COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 3 and 10

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 9" Cedar (1/4s NBT) N 54° W 36 Links

6" Soft Maple (1/4s NBT) N 84° E 11 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-established midway and on line between two original section corners. No evidence of original corner.

Corner was placed and witnessed September 2, 1960, with L. Rubick, Aide.

SURVEYORS SEAL

SIGNED

*Billy D. Buckler*  
REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 9/15/60