LAND CORNER RECORDATION CERTIFICATE

	ING REQUIREMENT Popewa Co.	Four Corners.	CH. F.A.1970
FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMB	ER
1. PUBLIC LAND SURVEY	N. T S., R	E	
		3-Sec.25 8-Sec.	
2. PROPERTY CONTROLL- ING IN SECTION-	25 ,T 50 K, R. 7	w.	
3. MISCELLANEOUS PROPERTY IN SECTION	,T, N. S., R	E.	
4. LOT NO, RECORDED PLAT			
5. PRIVATE CLAIMS		·	REGISTER OF DEEDS STAMP AND FILING NUMBER
I, Billy D, Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on, 19_75_, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on, 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:			
A. Description of original monument and accessories and/or subsequent restoration: 3-Sec.25 North 1/16 Corner, on Westside of Sec. 25. 5-Sec.25 North 1/16 Corner, of Section 25. 8-Sec.25 West 1/16 Corner, Section 25. 10-Sec.25 South 1/16 Corner, on Westside, Sec. 25.			
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: 3-Sec.25 Placed corner midway bet. Sec. Cor. to North and \(\frac{1}{4}\) Cor. to South. 5-Sec.25 Placed corner midway bet. \(\frac{1}{4}\) Cor. to North and Center Cor. to South. 8-Sec.25 Placed corner midway bet. \(\frac{1}{4}\) Cor. to West and Center Cor. to East. 10-Sec.25 Placed corner midway bet. \(\frac{1}{4}\) Cor. to North and Sec. Cor. to South.			
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Placed 1" pipe with 4" Aluminum cap at all corners.			
3_Sec.25 8" Jac1	pine, \$70°W, 5.9	and 5" Jackpine, N8	°E, 13.4'
5-Sec.25 8" Jac)	coine, S31°E, 16.9	and 8" Jackpine, S	47°W, 11.8'
8_Sec.25 8" Jac1	kpine, N43°E, 15.9	end 8" Jackpine, N	59°W, 3.61
10-Sec.25 6" W. I	Pine. S27°E, 55.2'	and 8" R. Pine, N54	W. 44.6 HILL DOALER
See Sketch on Reverse Side			
SIGNED BY Billy D. Buckler Silly O. Sachles DATE 12-17-75			
SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 (SEAL)			
FOR STATE AND UNITED STATES AGENCIES:			
SIGNED BY		DATE	
APPROVED AND SIGNED BYDATEDATE			
	MICHIGAN REGIST	ERED LAND SURVEYOR	(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO._