LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Chippewa Co.

2 Corners.

FOR CORNERS OF -: LOCATED IN -:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY T T N. R W.	J-4	
2. PROPERTY CONTROLL- 11 ,T. 50 N. R. 7 V.		
3. MISCELLANEOUS N. E. PROPERTY IN SECTION T. T. S., R. W.		
4. LOT NO, RECORDED PLAT		
5. PRIVATE CLAIMS		REGISTER OF DEEDS STAMP AND FILING NUMBER
Billy D. Buckler I,		
A. Description of original monument and accessories and/or st	ubsequent restoration:	
8-Sec.11 East 1/16 Corner of Section 11.		
J-4 Center Corner of Section 11.		
 B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: 8-Sec.11 Placed corner midway bet. Center Corner and East ½ Corner. 		
J-4 Placed corner midway bet. East and West 1 Corners.		
	,	•
•		
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Placed 1" pipe with 4" aluminium cap at both corners.		
8-Sec.ll Bearings: 16" W. Pine, N37°E, 12" R. Pine, S88°E,	8.9' and 10" R. Pine, 42.8'.	\$47°W, 48.5' and
J-4 Bearings: 5" R. Pine, S49°E, 12" J. Pine, N25°E,	45.4' and 6" W. Pine, 5.1' and 1" pipe, 54	\$25°E, 39.4' and
SIGNED BY Suckler SURVEYOR'S MICHIGAN REGISTRATION NO. 888	cheler DATE 9-10-7	BILLY D. BUCKLER LAND SURVEYOR SOLVEYOR
FOR STATE AND UNITED STATES AGENCIES:		LAND SUFFER
SIGNED BYCHIEF OF SURVEY PARTY	DATE	
APPROVED AND SIGNED BY DATE DATE		
(SEAL)		

SURVEYOR'S MICHIGAN REGISTRATION NO.__