LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Chippewa Co.

1 Corner

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	1
I. PUBLIC LAND SURVEY	T. 50 N., R. 7 W.	_L-3´	
2. PROPERTY CONTROLL- ING IN SECTION—	,T		
3. MISCELLANEOUS PROPERTY IN SECTION —	,T		
4. LOT NO, RE	CORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND
5. PRIVATE CLAIMS I, Gerald L. Wiggins , do hereby certify that under requirement			FILING NUMBER

- A. Description of original monument and accessories and/or subsequent restoration:
- L-3 North 1/4 Corner of Section 12. D.N.R. L.S. Billy D. Buckler placed a 1" pipe with 4" cap at this corner on 9-21-73. Bearings: 9" R. Pine, S47^OW, 42.6' 7" J. Pine, S33^OE, 1.9'
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner;
- L-3 Buckler replaced this corner from the remains of both O.B.T.'S. Buckler's 1973 7" Jack Pine has been cut. Marked new witt.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- L-3 Re-Witt D.N.R. Monument. Bearings: 12" R. Pine, N55°E, 87.4'
 8" R. Pine, N75°W, 58.7'
 10" W. Pine, West, 73.4'
 9" R. Pine, S47°W, 42.6'

SIGNED BY Gerald L. Wiggins

DATE 9-20-84

CURALD L. WINCINS
(SEAL) AND
SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO.

23521