## LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Chippewa

1 Corner

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	1
1. PUBLIC LAND SURVEY	T50 \$\text{N.} R7 \text{W.}	_K-3 ′	
2. PROPERTY CONTROLL- ING IN SECTION-	,TNE		
3. MISCELLANEOUS PROPERTY IN SECTION	,T		
1. LOT NO, R	ECORDED PLAT		
5. PRIVATE CLAIMS			
			REGISTER OF DEEDS STAMP FILING NUMBER

- A. Description of original monument and accessories and/or subsequent restoration:
- K-3 S.W. Section Corner of Section 1. Corner set by Billy D. Buckler, L.S. 9-21-73. DNR Monument. 12" J. Pine, S62°E, 58.8' & 6" J. Pine, S48°W, 40.6'.
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- K-3 Found 1" pipe with D.N.R. cap at corner location. Both of Buckler's bearing trees had been cut. Marked new witness.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-3 D.N.R. Monument. Wit: 10" R. Pine, \$72°W, 132.0' 8" R. Pine, \$45°W, 111.0'

8" R. Pine, S85°E, 82.0'

6" R. Pine, N76°E, 42.6'

SIGNED BY Gerald L. Wiggins SURVEYOR'S MICHIGAN REGISTRATION NO. 2352

DATE 10-10-85

FOR STATE AND UNITED STATES AGENCIES:

WIGGINS
LAND
SURVEYOR
No.
23521
LAND
LAND
LAND