## SURVEY & REMONUMENTATION

## MAR 24 2000 AND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

SE		Ti	$\cap$	١	Ì
- No.	w	8 8	S	и.	Æ

Clare County Remonumentatio 199900009779

			CLARE COUNTY MICHIGAN CAROL MCAULAY
For Corners in		1	On 11-10-1999 At 01:30 pm.
Clare		<u> </u>	LAND CORNER 9.00
(County)	Located In:	Corner Code#:	OR Liber 2 Page 58 - 5
1. Public Land Survey	T. <u>17N</u> R. <u>5W</u>	<u>H-7</u>	Instrument Liber F
•	T R		199900009779 OR 2
	T R		
2. Public Controlling S	T R		
in Section S	T R	· · · · · · · · · · · · · · · · · · ·	1210 00
3. Miscellaneous S	TR	i	# 369-99
Property in Section S	. T. R.		
	, Recorded Plat	·	Register of Deeds Stamp & File Number
5. Private Claims	, 1100011111111111111111111111111111111		,
L			
I. Mark R. Robison, in a field surve P.A. 74, Michigan P.A. of 1970, th conformance with regulations and instructions of the United States De decree of a Court of Law and/or the conformance with the rules of the N	e corner points mentioned in lir rules therefore as required in the epartment of the Interior, Burea at the corner points mentioned i Michigan Board of Land Survey	nes 1 and 2 above were in current manual of survey u of Land Management or by a n lines 3, 4 and 5 above were in rors or by a Decree of a Court of	1A B C D E F G H I J K L M 2 6 5 4 3 2 1 - 3 3 4 4 7 8 9 10 11 12 5 7 8 9 10 11 12 6 18 17 16 15 14 13
Law, established, re-established, m below.	onumented, re-monumented, re	covered, found as expressed	7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
			8 19 20 21 22 23 24
NOTE: Not more than 2 co		wn and range, may be	10 + 30 + 29 + 28 + 27 + 26 + 25
recorded on this certificate	•		
			12 31 + 32 + 33 + 34 + 35 + 36
A. Description of original restoration: 1837 Hodson, Set 1/4 Sec Post Birch 6" S67E 18, Pine 13 N56W (		ories and/or subsequent	
Circa 1900 Unknown, CSR 6-15 F. Post 5 - S3 ½W 61		10-2-72 Laphan LCRC #57 Same as (132) 1-249	5-15-75 McClung, (132) 1-919 Fd. Iron in Black Top
Tele Pole 9 - N70 1/2 E 60 1/2			
1949 Unknown, CSR 2-161		10-23-72 Verba LCRC #70 Fd 1/2" pipe & all MSHD Witnessese	11-25-77 Lapham, (132) 2-378 Fd. Mon. Box
Intersection of Hwy.		P-p	South 76.73 16" Oak
Cine 10(5 MOUD LIG to DAY DI		3-29-73 Urbaniak, (132) 1-459	\$25W 82.50 4" Oak
Circa 1965 MSHD US 10 R/W Plat Fd ½" Pipe in line w/fence N. 11.4"		Fd, Mon, Box Meas. 1317.30' West to 1/8 line	S45W 73.70 14" Birch Meas. West 2632,70 to G-7
N. edge of metal & 8.8 to S.E.M.			
Due South 77.85 28" Tr. Oak S62W 73.65 24" Tw. Birch		11-23-73 Lapham, (132) 1-624 Ref. LCRC #57	
11-17-69 Meyers, Unrec Survey	ı	6-26-74 Lapham, (132) 1-750	Lapham, Fd. Mon. Box 8-20-75 LCRC #208
References S1/4 Cor		References N1/4 Cor Sec 22	12-03-80 (132) 2-710
0-16-70 Lanham Haras Survey		Meas. 1322.38' East to 1/8 Cor	5-27-81 (132) 2-650 9-03-82 (132) 2-719
9-16-70 Lapham, Unrec Survey References S1/4 Cor Sec 15		2-7-75 Meyers, (132) 1-971	5-02-88 Unrec Survey
4-12-72 Urbaniak, (132) 1-249		Fd. Mon. Box Meas. West 1316.35 to 1/8 Cor	
N05°E 34.94 X.E. End Hdwl	·		
S05°W 38.90 X.E. End Hdwl			
See dossier for detailed repo	rt.	d applied in restoring or re-es	tablished corner:

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 36" rerod with Clare Co. Remon Cap marked P.S. #27458 in existing Mon. B	ox. Accepted as best available evidence of the
accepted position of the corner.	APPROVED LAND CORNER

Witnesses:

N41°W, 56.38 N & T in P. Pole

South 77.55 N & T in Twin 30" dead oak (OBT)

S25°W 76.73 N & T in Twin 16" x 11" red oak (OBT)

S62°W 77.20 N & T in 6" red oak

S01°W 77.10 N & T in 10" W. P

Surveyor's Michigan License No.

ROBISON **PROFESSIONAL** SURVEYOR

Clare County

Chairman 2

P.A. 345 of 1990

ED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN.28, 1971