SURVEY & REMONUMENTATION

JAN 2 3 1998

Surveyor's Michigan License No.___

CLARE COUNTY REMONUMENTATION

SECTION For corners in	LAND CORNER RECORDATION CERTIFIC Filing Requirement of Act 74, Mich. P.A. 1	970 🗸
	<u>†</u>	#261-92
CLARE Loca	ited In: Corner Code #	# 261-97 97 CEC 30 FII 2: 21
1. Public Land Survey	T_17N R 5W	REGISTER OF DEEDS CLARE COUNTY CAROL A. MCAULAY
2. Property Controlling Sin Section S	TR	Register of Deeds Stamp & File Number
4. Lot No, Recorded Pla 5. Private Claims	it	ABCDEFGHIJKL
o. t mate diame		2 6 5 4 3 2
requirements of P.A. 74, Michigan P.A. of conformance with regulations and rules the United States Department of the Interior, But that the corner points mentioned in lines 3	ield survey on <u>De C./5</u> , 19 97 do hereby state that under 1970, the corner points mentioned in lines 1 and 2 above were in refore as required in the current manual of survey instructions of the ureau of Land Management or by a decree of a Court of Law and /or, 4 and 5 above were in conformance with the rules of the Michigan e of a Court of Law; established, re-established, monumented,	3 4 - 7 - 9 - 9 - 10 - 11 - 12 5 6 - 18 - 17 - 16 - 15 - 14 - 13
NOTE: Not more than 2 corners, all in on this certificate.	n the same town and range, may be recorded	9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
A. Description of original monument 1837 Hodgson Set 1/4 Section Post WitBeech 12" N12W 37 B. Oak 22" S22E 27 circa 1900-CSR 6-35 Tile cinders & sta	and accessories and/or subsequent restoration: 3-05-79 Fluharty-LCRC#343 Set 5/8" x 18" C.I. East 75.12' from N 1/4 Cor Sec 2, T16N, R5W, in center- line of old 2-track, 1' East of North Rence line, 22' South of West Fence	4-21-87 Lapham(132)2-976 Found 1/2* C.l. Witsame witnesses as LCRC#16 N33.0 Fence Corner Measured 2632.94 West to H-13
Wit-B Oak 20" NE 7 J-13 to I-13=40.4 10-19-71 Lapham-LCRC#16 SE cortor pointed stone at intersection fences. WitS45W 22.0 5" Maple	08 Ilne, equal distance on-line WitN54W 32.67 24" Oak	4-13-87 Lapham (132) 3-318 Witsame as (132) 2-976 12-18-97 Lapham Set 1/2" x 18" rerod from LCRC#16
S30W 19.2 12" Maple	340E 13.90 6 Popiai	Witsame as (132) 2-976
B. Description of corner evidence fo	aund and/or method applied in restoring or reestablishing co	orner:
Found 1979 Fluharty comer & witness indication of a fence intersection or the Measured 2632.94.).	ses. It appears 1971 Lapham comer is not J-13 since this come stated witnesses at this point. Accepted Fluharty comer. Me	easured 2636.34 West to I-13 (PBL 1987
See dossier for detailed report		APPROVED LAND CORNER P.A. 245 of 1990 Claro County Chairman fauls for
	•	
		Dale 12-23-97
C. Description of monument for corne	er and accessories established to perpetuate locating the p	osition of the corner:
	County Remonumentation Cap marked P.S.#27458. Accepted	d as best available evidence of accepted position
of the corner.		A SE OF MION
Witnesses: N47W 32.85', nail & tag, 30" R. Oak S49W 30.46', nail & tag 14" Maple S20W 28.0', nail & tag, 26" Twin Mapl S11E 49.54', nail & tag, 22" Maple	le	MARK R. ** ROBISON & PROFESSIONAL & SUBMEYOR
Signed by Monu (Marsy Date 12	-22·97