

JAN 17 1996

LAND CORNER RECORDATION CERTIFICATE COMMISSION Requirement of Act 74, Mich. P.A. 1970

For corners in		•.	1		12.30	, O1	٠ ٠	المريك الرمسوا
CLARE	Located In:	Corner Code #			736			
(County)					Ç.		رې ښ) · · · · ·
1. Public Land Survey	T <u>17NR 5W</u> TR TR	M-11		×	į.	37 °S	<i>'</i> O	
Property Controlling in Section Miscellaneous Property in Sec.	TR S TR S TR S TR			Register c	of Deeds Sta	ımp & F	ile N ur	mber
4. Lot No, Recor	rded Plat							;
				A B C I	DEFG	HI	JK	LM
•				2 6	54		- 2 - 	
I, MARK R. ROBISON, in a field survey on OCTOBER, 19 95 do hereby state that und requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were conformance with regulations and rules therefore as required in the current manual of survey instructions of t United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan				3 4 7 5 6 -18	8 9 9 16 1	-10	-11 -14	12
Board of Land Surveyors or by recovered, found as expressed be	a Decree of a Court of Lav	v, established, re-establishe	d, monumented,	7 8 19 2				
, ,		d managa manaha sagardad		9 19 2			_23	
on this certificate.	ners, all in the same town and	a range, may be recorded	•	10-30-2	928		-26	25
				11			-	
			•	12 31 -3	233	_34	_3 ^l 5	36
A. Description of original mo	nument and accessories a	nd/or subsequent restore	ion:	13				
1837 HUDSON WITHEMLOCK 10" S2 HEMLOCK 10" N5	8W 16 4W 21	10-19-71 PAUL FOUND 1" IRON WITCEDAR 6" I MAPLE 7" :	LAPHAM, L.C.R.C 145°E 36.4' 860°W 42.4'	FOUND 1	3 urbaniak 1" iron Es same as			D SURV
	GRANT, GOV'T, COR. FOUN	ID, CSR CHERRY 14' LAPHAM DWG IND	' S20°E 28.3' ICATES MEAS. S	2640.57' TO N	1 –12			
NO DATE OR SURVEYOR WITHEMLOCK 10" S5 W.P. STUMP 20"	R 9°W 16, S40 1/2"E 16 1/2, CSR	7-18-72 COURT FOUND 1" IRON WITNESSES SAME						
B. Description of corner evid	dence found and/or method	11-5-74 PAUL 1 AS RECORDED IN dapplied in restoring or re	7-18-72 L.C.R				•	ı
FOUND 3/4"x18" PINC	CH PIPE AND 1971 WITNES	SES IN CENTER OF ABAN	DONED N-S ROA	AD ON FENCES	EAST AND 1	WEST.		
·			·	APPROVE P.A. Ci	D LAND C 345 of 19 are County	90	R	
This Corner establis	hed in Clare County Ro	emonumentation Progr	om.	Chalrman_	faul	1.10	Zh	
See dossier for det	ailed report.			Date	2-12-9	5		
C. Description of monument M-11: 25-36 SECTION SET 5/8"+36" RE-RO	for corner and accessories CORNER ON TOWNSHIP L D WITH 3" CLARE COUNTY	· · ·	locating the pos	sition of the corr	ner:	MICHI	ġ,	
ACCEPTED AS BEST AV. N35°E 36.74' — S60°W 42.30' — S20°E 28.30' —	NAIL & TAG IN 10" CED/ NAIL & TAG IN 9" MAPLI NAIL & TAG IN 20" CHEF NAIL & TAG IN CORNER FI	ACCEPTED POSITION OF AR (OBT) E (OBT) RRY (OBT)	THE CORNER.	# TICEN	MAR ROBI PROFES SURVI No 274	SON SIONAL EYOR D.	MANETON * THE	
Signed by MANY)(logisal		Date 12	-12-0C				
Signed by //////	10 27ACA		Date	12 7 5				
Surveyor's Michigan License I	NO. 27732	1						I

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995