LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -: LOCATED I		CORNER CODE NUMBER		
L PUBLIC LAND SURVEY T. 17	i, R. <u>5</u> w.	E-9; D-11	_	
2. PROPERTY CONTROLL- 29 ,T. 17 N	5 w.	16; 11; 12	_	
3. MISCELLANEOUS NOTICE TO SECTION TO THE SECTION TO SE			_	
4. LOT NO, RECORDED PLAT_			-	
5. PRIVATE CLAIMS			REGISTER OF DEED	DS STAMP AND
the corner points mentioned in lines 1 and 2 ab re-established, monumented, re-monumented, r and rules therefore as required in the current r Bureau of Land Management or by a decree of and 5 above were, in a field survey on as expressed below and in conformance with the Decree of a Court of law: XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	pove were, in a freecovered or restraintal of survey a court of law. The rules of the Mark of the Mar	ield survey on	and in conformance value of States Department repoints mentioned restored, established of gistration for Land Sur	30, established. with regulations of the Interior. 1 in lines 3, 4 or re-established
	dure for the	e suparvision or se	ections.	
C. Continued:	1	1	12	
Set 5/8" rod w/RLS cap S	et 5/8" rod	'	Set 5/8" rod	
Set 5/8" rod w/RLS cap S 4" Maple S37°E 32.2' 8 3" Maple N58°E 13.7' 3	" Cherry " Maple in clump	S48°E 10.4' 1 S38°W 20.6' 5	18" Oak S83° 5" Maple N33°	PW 44.9' PW 34.7'
E-9 Restored corner from what we condition. Unable to locate a particular in line with fence D-11 Set this cor. midway bet., and identify any previous mon. and the South line of Sec. 29. How Johnson survey & subsequent lothen established, and felt thing Set by standard survey procedum Set by standard survey procedum C. Description of monument for corner and according to the standard survey procedum C. Description of monument for corner and according to the standard survey procedum C. Description of monument for corner and according to the standard survey procedum control of the standard survey proce	revious mon South and in line wi this posit ever it is cal surveys s was best re for the re for the	ument, but may have North. th old fences runn ion must admit to offelt this situation, & fences construction of section o	e been removed ing North & Soutcausing some dis n was established ted according to oper location fo tions.	in road con- th. Unable to stortion to ed by the 1903 to the corner or corner.
E-9			D-11	
Set DNR mon. PK nail, 18" Maple S55°E 45 PK nail, 7" Beech N54°E 46	2.7'	DNR mon. 3" Blk. Locus 3" Blk. Locus	t N15°E t S40°E	12.1' 4.7'
SIGNED BY LEWILL DE	Thing	DATE	3-12-8	OF Mich
SURVEYOR'S MICHIGAN REGISTRATION	1006	8	(SEAL)	
FOR STATE AND UNITED STATES AGEN				Company of Care
		INA PE	,	"Manney See
SIGNED BYCHIEF OF SUR	VEY PARTY			
APPROVED AND SIGNED BY	GAN REGISTERED LA	DATI	(SEAL)	
			CLARE COUNTY	
SURVEYOR'S MICHIGAN REGISTRATION		PROVED BY MICHIGAN STATE	BOARD OF REGISTRATI	ON, JAN. 28, 1971 SED MAY 14, 1975