REMONUMENTATION

JAN 2 3 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Clare County Remonumentation

For Corners in		1	CLARE COUNTY MICHIGAN CAROL MCAULAY
Clare (County)	Located In:	Corner Code#:	On 11-29-2000 At 10:31 LAND CORNER 9.00 OR Liber 2 Page 23
1. Public Land Survey	T. <u>17N</u> R. <u>4W</u> T. <u>17N</u> R. <u>3W</u> T. R.	M-13 A-13	Instrument L 20000009702 OR
2. Public Controlling in Section	S T R S T R		
3. Miscellaneous Property in Section	S T R S T R		#437-00
4. Lot No 5. Private Claims	, Recorded Plat		Register of Deeds Stamp & File
I, Mark R. Robison, in a field s P.A. 74, Michigan P.A. of 1970	urvey on May 9, 2000, do hereby certif	fy that under requirements of	₁ ABCDEFGHIJKLM

conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

This is a single corner common to T17N, R4W, & T17N, R3W.

A. Description of original monument and accessories and/or subsequent restoration:

GLO, Hodgson, 1837

Sugar 16" N35°W, 11 LINKS

Sugar 18" S65°E, 47 LINKS

C.S.R. Unknown, Circa 1900 Bk 5. Pg. 180

Mile Post 12" S55°W, 63 LINKS

C.S.R. Johnson, 1903, Bk. 4 Pg. 31 Stake and stones Stump S45°E, 26 LINKS A-13 to B-13 45.59 chains

Lapham, 1972 LCRC #56-72

3 witnesses

Survey, Lapham, 1972 Not recorded 3 witnesses same as LCRC #56-72

M-13 to L-13 = 2639.65

2000000009702 Filed for Record in 1 am. 32 - 232

iber Page

Number

14	4]	3 (_	D l	E 1	F (G l	H 1		[]	ΚI	[ر	M
2	- 6	5 -		5	,	1 4	 -:	3	- 2	2]	-	
2 3 4 5 6 7	. •	7	:	} 8·	-	 9	1	0	1	1.	1	2	
5	1	8-		7	 - - 1	6	1	 5		1	1	2-	
								ļ				_	
8 9	- I	9	4	0		1-	- 2	2			Н	4	
10 11	- 3	0-	- 2	9-	- 2	28- 	- 2	?7- ⊢-	- 2	6-	- 2	5-	
12	- 3	1	- 3	2-	- 3	3-	- 3	4-	- 3	5-	- 3	6-	
13	ر _	1) <u></u>) J		L	_3	3	د	0	

LCRC Isabella Co. Robison, 1997 Remonumentation L1. Pg. 207

Numerous Isabella Co

surveys detailed. 4 witnesses with 2

the same as LCRC #56-72

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner.

No evidence of GLO or CSR surveys. Found Isabella County standard remonumentation corner. Found 2 witnesses from LCRC #56-72 and 4 from 1997 LCRC. Accepted found monument as best available evidence of accepted position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Found iron with Isabella Co. Remon Cap in Mon. Box.

Witnesses:

S60°E, 59.83' - N & T in 17" Maple (OBT) N46W, 44.07' - N & T in Power Pole S60°W, 103.79' - N & T in 20" Maple (OBT)

S78°E, 132.45' - N & T in 20" Maple (OBT)

ROBISON ROFESSIONAL SURVEYOR

APPROVED LAND CORNER

P.A. 345 of 1990

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN.28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983