SURVEY & REMONUMENTATION

JAN 2 3 2001

LAND CORNER RECORDATION CERTIFICATE

SECTION

Filing Requirement of Act 74, Mich. P.A. 1970

Clare County Remonumentation

For Corners in Clare (County)	Located In:	Corner Code#:	Filed for Record in CLARE COUNTY MICHIGAN CAROL MCAULAY On 12-15-2000 At 07:44 am. LAND CORNER 9.00 OR Liber 2 Page 301 - 301
1. Public Land Survey	T. <u>17N</u> R. <u>4W</u>	E-3	0. 51951 F Fade 361 - 361
	T R T R		Instrument Liber Pa 200000010178 OR 2 3
2. Public Controlling in Section	S R		£ 506-00
3. Miscellaneous Property in Section	S R		
4. Lot No 5. Private Claims	, Recorded Plat		Register of Deeds Stamp & File Number
I, Mark R. Robison, in a field s	urvey on November 27, 2000, do here	by certify that under	- _l abcdefghijklm
requirements of P.A. 74, Michig	gan P.A. of 1970, the corner points me	entioned in lines 1 and 2 abov	

I, Mark R. Robison, in a field survey on November 27, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines I and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

7 10 12 6 7 8 9 18 16 19 24 20 22 23 21 10 30 29 28 27 26 25

A. Description of original monument and accessories and/or subsequent restoration:

GLO, Burt, 1850 Set Post Hemlock 12" East, 6 LINKS Maple, 10" S12°W, 5 LINKS

CSR, Johnson, 1907, CSR Bk. 4 Pg. 90 Pine stump 40" S45°W, 19 LINKS E-3 to F-3, 39.50 chains

CSR, Johnson, 1910, CSR Bk. 5 Pg. 153 Same as CSR 4-90 Survey, MDOT, 1970, Unrecorded Survey Found 3/4" pipe 2' East of fence to South and

3' South of C.L. E-W road Two witnesses

E-3 to F-3, 2636.50 feet E-3 to E-4, 2634.45 feet

E-3 to D-3, 2659.63 feet

APPROVED LAND CORNER

Page

P.A. 345 of 1990

Clare County

Nu 12-13-00

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner.

Found 3/4" x 18" pipe 3 feet South of C.L. Road & 2' East of fence to South. Did not find any witnesses. Verified MDOT distances to D-3 and F-3. Accepted 3/4" pipe as best available evidence of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 36" rerod with Clare County Remon Cap marked P.S. #27458. Witnesses:

North, 36.54' - N & T in 8" Cherry

N59°E, 52.20' - N & T in 10" x 18" Twin Ash

S64°E, 70.09' - N & T in 8" Ash

S04°W, 35.57' - N & T in Corner Fence Post

MARK R.
ROBISON
PROFESSIONAL SURVEYOR
IVO.
27458

Signed by Man Q Cos. 5

Date 12/14/2000