_	GURYEY &
(.	ACTOR OF THE PROPERTY OF THE PARTY OF THE PA
	ON HENTATION -

FEB 1 8 1994

CLARE COUNTY REMONUMENTATION PROGRAM $^{\cite{E}}$

2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	أسادس	William	300	1 . 37
---------------------------------------	-------	---------	-----	--------

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

100-		~	-
1993 DEC	20	Đi.	
1993 DEC	-0	PM	1:46
MEGISTE	वि भ	0~-	. •
REGISTER CLARE DONNA	Con	UL E	DS
WMMM	M. C	AD	L.
			17

For	corners in					
	CLARE		Located In:	Corner Code ≠		
	(County)		Coodica III.	· ·		
1.	Public Land Survey		T 17N R 4W	G-7		
			T R	· · · · · · · · · · · · · · · · · · ·		
			T R	afit.		
	٠. ,		T R			
2.	Property Controlling	s	T R			
	in Section	S	T R			
3.	Miscellaneous	s	T R			
	Property in Sec.	s	T R			

Register of Deeds Stamp & File Number

4.	Lot No, Recorded Plat
ā.	Private Claims
•	

OCTOBER MARK R. ROBISON , in a field survey on . 10 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same lown and range, may be recorded on this certificate.

10 11 12

Description of original monument and accessories and/or subsequent restoration: 1850 W.A. BURT, POST, 11-30-02, HARPER, 4" CEDAR STAKE, HEMLOCK STUB 20", N 70°E, 24 LKS, CSR 4-11 4-15-03, JOHNSON, STAKE & BRICKS, CSR 1-15 10-19-71, URBANIAK, LCRC 11-71 5-1-72, LAPHAM, LCRC 25-72 8-18-79, SEDGEMAN, (132) 2-490

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 18" x 1/2" SQUARE BOAT SPIKE (1" DIA. HEAD)
FOUND RECORDED WITNESSES:
SE, 101.95' — N.W. COR. TWP. HALL
SW, 63.07' — POW. POLE
NE, 46.88' — FENCE POST

This Corner established in Clare County Remonumentation Program. See dossier for detailed report.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET 5/8" X 36" RE-ROD WITH 3" CLARE COUNTY MONUMENT CAP.

S 55%, 64.41' - POWER POLE

S 50°E, 101.75' - N.W. COR, TWP. HALL

N 50°E, 49.68' - POWER POLE

N 50°W, 104.1' - N.E. COR. 1 CU.YD. STONE

ATE OF MICH MARK R. ROBISON ROFESSIONAL SURVEYOR No. 27458 OFESSION Common of

Mana Signed by .

Surveyor's Michigan License No. _

Date _