LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	ig Requirement of Act 74, Wich. P.A. 1	970
CLARE Located In:	Corner Code #	RECONSTRUCTION OF THE PROPERTY
1. Public Land Survey T 17NR T 17NR T R	4W M-5	# 167-96 96 NO7 14 Til 4: 17
7 R 2. Property Controlling S T R in Section S T R		REGISTER OF LEEDS CLARE COUNTY DONNA M. CARE
		.
		Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat		A B C D E F G H I J K L 1
5. Private Claims		1 2 6 5 4 3 2 1 -
MARIA R. PORICON	ALICHET OF	3
I, MARK R. ROBISON , in a field survey on requirements of P.A. 74, Michigan P.A. of 1970, the corn conformance with regulations and rules therefore as require United States Department of the Interior, Bureau of Land N that the corner points mentioned in lines 3, 4 and 5 above Board of Land Surveyors or by a Decree of a Court of recovered, found as expressed below:	er points mentioned in lines 1 and 2 above were in ed in the current manual of survey instructions of the flanagement or by a decree of a Court of Law and for were in conformance with the rules of the Michigan	6 18 17 16 15 14 13
NOTE: Not more than 2 corners, all in the same tow on this certificate.	n and range, may be recorded	9 29 28 27 26 25
		12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration: 1837 HODGSON WIT.— SET POST. BEECH 8" S65% 13 LKS. HEMLOCK 14" N68% 13 LKS. 1850 BURT 9-27-84 LAPHAM, L.C.R.C. #462 WIT.—FOUND 1/2" RE—BAR. S50%, 49.25' — TELE. POLE. S45%, 45.81' — FENCE POST. N50%, 49.29' — FENCE POST. N50%, 49.41' — COR. POST. S50%, 49.41' — COR. POST.		
WITINT N&S LINE AT POST. HEMLOCK 22" N85E 73 LKS. PINE 20" S83E 60 LKS. 1850 BURT WITSET POST (SAME AS TWP. LINE SURVE	S45°W, 49.42' - FENCE POST.	7-1-91 WILCOX WITFOUND 3/8" REBAR, SET 3/8" RE-BAR WITH CAP IN MON. BOX. S47°E, 47.17' POWER POLE. S54°W, 49.56' COR. FENCE POST. N21°W, 54.36' COR. FENCE POST.
WITN30°W, 49 LKS, TELE. POLE 8". MEAS, EAST, 3011.59' TO 8-5. N24°E, 87.05' - POWER POLE. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:		
FOUND 1/2" IRON IN MON. BOX. FOUND TWO OLD WITNESSES.		
See dossier for detailed report.	•	
C. Description of monument for corner and access	sories established to perpetuate locating the p	position of the corner:
SET 5/8"x36" RE-ROD WITH 3" CLARE CO ACCEPTED AS BEST AVAILABLE EVIDENCE OF	DUNTY MONUMENT CAP. F THE ACCEPTED POSITION OF THE CORNER.	" WELLO STATE OF THE STATE OF T
WITNESSES: \$60°W, 49.40° — NAIL & TAG IN T.F \$50°E, 47.12° — NAIL & TAG IN PO N50°E, 60.32° — CENTER OF PIPELII	WER POLE (OBT). NE MARKER.	P.A. 345 of 1990 Clare County Chairman facts.
N29℃, 87.08' — NAIL & TAG IN PO	WER PULE.	Date
Signed by Many Cobission Surveyor's Michigan License No. 27458	MARK R. ** ROBISON ** Date ** PROFESSIONAL ** NO.	10-1-96
;	27458 27458	HIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 19 REVISED MAY 14,19
	250000000000000000000000000000000000000	REVISED JAN., 19 REVISED OCT., 19