## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

|                                 | •  | ·                                   |                                       |
|---------------------------------|--|-------------------------------------|---------------------------------------|
| For corners in                  |  |                                     |                                       |
| Clare                           | Located In:  | Corner Code #                       |                                       |
| (County)                        | -  |                                     |                                       |
| 1. Public Land Survey           | T <u>17N</u> R <u>4W</u><br>T R  | E11                                 |                                       |
| 2. Property Controlling         | S TR   |                                     |                                       |
| in Section                      | STR  |                                     |                                       |
| 3. Miscellaneous                | STR  |                                     |                                       |
| Property in Sec.                | S TR   |                                     | Register of Deeds Stamp & File Num    |
| 4. Lot No, R                    | ecorded Plat   |                                     | ABCDEFGHIJKLM                         |
| 5. Private Claims               |  |                                     | 2 6 5 4 3 2 1 1                       |
| I. Craig W. McVean . in         | a field survey on _August, 10, 19 _9   | 9 do                                | 4 - 7 8 9 10 11 12                    |
| hereby state that under require | ments of P.A. 74, Michigan P.A. of 1970,   | the                                 |                                       |
|                                 | s 1 and 2 above were in conformance with   |                                     |                                       |
|                                 | as required in the current manual of survey<br>as Department of the Interior, Bureau of La |                                     | 6 - 18 - 17 + 16 - 15 - 14 + 13 - 1   |
|                                 | a Court of Law and /or that the corner poi   |                                     |                                       |
| mentioned in lines 3, 4 and 5 a | bove were in conformance with the rules  | of the                              | 819 20 21 22 23 24                    |
|                                 | ors or by a Decree of a Court of Law; esta   | ıblished,                           | 9                                     |
| re-established, monumented, re  | ecovered, found as expressed below:  |                                     | 10 30 -29 - 26 27 - 26 25             |
|                                 |  |                                     | 11                                    |
| NOTE: Not more than 2           | corners, all in the same town and re   | nge, may be recorded on             | 12 -3132 33 - 34 35 36                |
| this certificate.               | onio, an in the dame to the area.  | <b>g.,</b> ,                        | 13                                    |
|                                 |  |                                     |                                       |
| A. Description of original      | monument and accessories and/or su   | bsequent restoration:               |                                       |
| E11- GLO - set post - G.        | H. Cannon - 1850   |                                     |                                       |
| Hemlock 6" S5°W 1               |  |                                     |                                       |
| Beech 9" N38°W 10               |  |                                     |                                       |
|                                 | . 4 - p. 13 - W. Harper - 1902   |                                     |                                       |
| Cedar stake & ti                | n .  |                                     |                                       |
| - CSR, BK.4 - p. 17             | 7 (MDOT?) - %" pipe in post surrou   | nded by stones. Hacked H            | ubs                                   |
| Forward left - N                |  |                                     |                                       |
| Forward right N                 |  |                                     |                                       |
| Rear right 19.36                |  |                                     |                                       |
| Rear left 11.65                 | US-10 - 1935 - shows corner & tie  | to centerline US-10                 |                                       |
|                                 | p. 11 – 1987 – P.B. Lapham   | to centerino ou ro                  |                                       |
| ,                               |  |                                     |                                       |
| B. Description of corner e      | vidence found and/or method applied  | I in restoring or reestablishi      | ng corner:                            |
| E11- Sec. Cor. Common           | to Sec. 28,29,32&33 - FND ¾" I.D   | . iron pipe – Up 1' <u>+</u> - with | some stones around at intersection of |
| old down fences S. N & V        | / - fits MDOT tie to centerline US-10  | ) within reason. FND ½ " C          | IR #27458, 427.3' South & 0.77' E of  |
|                                 | 10. Rec. survey shows 429'. Calc.  | MDOT Plans as 429.64'.              | Pipe accepted as the best available   |
| evidence of the position of     | f the original corner.   |                                     |                                       |
|                                 |  |                                     |                                       |
|                                 |  |                                     |                                       |
| C. Description of monume        | ent for corner and accessories establi   | shed to perpetuate locating         |                                       |
|                                 | more stones around.  |                                     | ANTE OF MICHIGAN                      |
|                                 | ail and tag in E side 12" White Pine   |                                     | CRAIG W.                              |
|                                 | ail and tag in E side 24" White Pine   |                                     | McVEAN A                              |
|                                 | ail and tag in N side 16" White Pine ail and tag in W side 6" Scotch Pine                  |                                     | PROFESSIONAL                          |
| North 1' set Orange             |  |                                     | SURVEYOR ON No.                       |
| North 111' to CL. F             |  |                                     | No. 39088                             |
|                                 |  |                                     |                                       |
|                                 |  |                                     | A OFE SSIONAL                         |
| ♠ '                             | n n n:   |                                     | 2330                                  |
| Stand by United                 | ON Ull Ilen  | -                                   | Date 10/18/2000                       |
| Signed by                       | . Join Desc  |                                     | Data                                  |
| Surveyor's Michigan Licen       | se No. <u>39088</u>  |                                     |                                       |