LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 18 N. S., R. 06 E. W.	D-5, E-5, E-6
2. PROPERTY CONTROLLING IN SECTION	T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION 08	T. 18 N. S., R. 06 E. W.	*1490.9' W OF E-5

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, CARL F. ROSER, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on FEBRUARY 11, 1985, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. (CONTINUED)

~~A. Description of original monument and accessories and/or subsequent restoration:~~

E-6

FD 1 1/4" PIPE IN CTR GR RDS N-S-W.

18" MAPLE	N50°W	85.54
8" R PINE	N85°E	52.52
16" BL CHERRY	S50°W	40.35
SET CED POST W/LOC TAG BESIDE FD IR.	DUE E	33'

*

FD 5/8" IR ROD W/RLS CAP; ADDED CED POST W/LOC TAG.

12" B CHERRY	N40°E	46.40
9" R PINE	N75°E	46.40
FD 1" BOLT CTR M-115	N86°34'W DUE W	27.54 92.3

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

D-5 FD M MCCLUNG ROD WITH CAP INSIDE 3 X 20" PIPE FOR S 1/4 COR OF SEC 8. ALSO 1 1/2" BY 6" PIPE DROVE IN SWP. BESIDE CORNER.

E-5 FD 1/2" ROD FOR SE COR OF SEC. 8. FITS M MCCLING WITS.

E-6 FD AND ACCEPTED 1 1/4" PIPE IN GRAVEL ROAD INTERSEC FOR E 1/4 COR OF SEC 17. FD IR 33'-E BY RLS, PAUL LAPHAM.

* FD 5/8' ROD WITH RLS CAP, M MCCLUNG, ON S LINE OF SEC 8 INTERSEC WITH E'LY R.O.W. LINE OF M115.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-5

FD 3"X 20" PIPE; ADDED DNR MON & CED POST.

*6" MAPL(CLP OF 4)	S10°W	53.0
16" OAK	S10°E	89.5
FD 5/8" X 18" IR FLUSH	S11°W	126.4±.3
EDGE SWAMP	DUE E	300'±20'

*M.M. WIT

E-5

FD 1/2" RE-ROD.

12" CEDAR	N35°W	84.0'
8" MAPLE	N55°E	48.6'
9" MAPLE	N85°E	54.2'
12" CEDAR	S40°W	63.9'
CTR N-S GR RD	DUE E	6'
SET CED POST W/LOC TAG.	DUE W	33'

SIGNED BY Carl F. Roser DATE 01-13-86

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FREEMAN TWP
CLARE COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET