For corners APR 0 6 1995

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

• .	*
f.,	RECEIVED
94	DEC 29 AM 8: 47
RE(C DO	HSTER OF DEEDS LARE COUNTY

_	CLAREONIMIC	Located In:	Corner Code ##		REGISTER OF DEEDS CLARE COUNTY DONNA M CARR								
1.	Public Land Survey	T1 <u>8N</u> R <u>5W</u> T R T R T R	B-7					, i · j	GĄ	RR			
2.	Property Controlling	S T R											
	in Section	S T R											
3.	Miscellaneous	S T R		Rea	ister o	f De	ede !	Stan	nn &	File	Nur	nher	,
	Property in Sec.	S T R							.p <u>u</u>				
4.	Lot No , F	Recorded Plat				B C	n	£ !	. .	н	1 .1	ı K	t
5.	Private Claims				<u>î</u>	ĬĬ	Ť	1	Ť	ï	H	m	Ť
		^			²├-	6	- 5	+-	, ——	- \$ —	1-7	≥	-1-
-					3	\vdash		+	-	+-	╂╌┤	-	
					4	┦┸	- k-		<u>, </u>	-10—	 —₁'	<u>'</u> 1——	{2-
١, "		, in a field survey onDECEMBE			5	\sqcup		$\downarrow \downarrow$		4-	4	$\sqcup \downarrow$	
do	hereby certify that under rec	quirements of P.A. 74, Michigan P.A. o	of 1970, the corner points mentic	oned	اء	l l	L		L I	L		1	

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1856 CANNON, G.L.O.
POST (NOTE STATES OLD CORNER IS N18°E 382 LINKS)
WIT.-HEMLOCK 12" N23°W 37 LKS,
TAMARACK 10" S65°E 46 LKS.

C.S.R. NONE

NO RECORDED SURVEYS

NO L.C.R.C.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND NO EVIDENCE OF CORNER. TRAVERSED AROUND SECTION 18 AND SET POINT ON SINGLE PROPORTIONATE MEASURE BETWEEN A-7 & C-7. G.L.O. MEASURE IS 80.76 (5330.16). WE MEASURE 5248.23. WE SET C-7 2599.42 FEET WEST OF B-7. CORNER FELL IN MARSHY AREA. WE SEARCHED FOR O.B.T'S., BUT DID NOT FIND ANY.

P.A. 345 of 1990
Ciare County

10

Chairman Han S. Lyhn Date 12-19-94

This Corner established in Clare County Remonumentation Program.

See dossier for detailed report.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET 5/8" X 36" RE-ROD WITH 3" CLARE COUNTY MONUMENT CAP IN MONUMENT BOX.

WITNESSES: \$10°E 33.14" - NAIL & TAG IN 6" BALSAM \$30°W 21.70" - NAIL & TAG IN 6" BALSAM N45°W 94.07" - NAIL & TAG IN 8" MAPLE \$30°E 78.07" - NAIL & TAG IN 4" OAK

MARK R.

* ROBISON

CO PROFESSIONAL

SURVEYOR

No.

27458

Signed by Man Const S

Date 12-19-94

Surveyor's Michigan License No.

27458

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN.. 1983