REMONUMENTATION For corners in COMMISSION

LAND CORNER RECORDATION CERTIFICATION Filing Requirement of Act 74, Mich. P.A. 19

RECEIV	مسأ	نها	
FIFID	A	. [
E T 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	AH	8:	47

Miscellaneous

Property in Sec.

2.

CLARE (County)	Located In:	Corner Çode ≠#	
Public Land Survey	T1 <u>8N</u> R5W	M-7	
	TR	· · · · · · · · · · · · · · · · · · ·	
Property Controlling	S T R		
in Section	S T R		

___ T ._

REGISTER OF BEEDS CLARE COUNTY DONNA M CARR

Register of Deeds Stamp & File Number

		·
4.	Lot No, Recorded Plat	
5.	Private Claims	

___ R _

MARK R. ROBISON , in a field survey on NOVEMBER . 19 94 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

1838 NICHOLSON SURVEYED TOWNSHIP LINES

NOVEMBER 1856 CANNON WIT.-(1)PINE 38" S17W 47 LKS. (2)ASPIN 12" NW 15 LKS.

11-23-07 JOHNSON WIT.-NORTH 1/4 COR.-GOV*T WIT. STATES CORNER FOUND AT N(S.W.), I(S.E.) & E(N.E.)

11-21-13 C.S.R. L.6-PG.60 WIT.-(1)PINE 36" S17W 43 LKS. (3)PINE 30" S55W 67 LKS. (4)PINE 28" N66W 108 LKS.

L.C.R.C. - NONE

REC. SURVEYS - NONE

NOTES SHOW FENCE CORNER 33'N OF CORNER & 3 O.B.T.'S AS FOLLOWS:

WIT.-W.P. STUB-20" S18 1/2"W 47 LKS. O.B.T.

W.P. STUB-18" N27"E 75 LKS. O.B.T.

24" - N31°E, 119 LKS. 3-66 LAPHAM, UNRECORDED SURVEY & NOTES

MUELLER (132) L.3-PG.21 NO WITNESSES.

10

11

12

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

TRAVERSED FROM K-7 TO K-8 & DIAGONALLY ACROSS SECTION L-7 & M-7, FOUND K-7 TO L-7 TO BE 2652.90 (REC. 2658.2 & CALC. 2655.36 - 1966 DATA) & L-7 TO M-7 TO BE 2631.8 (REC. 2632.2). FOUND 3/4" SUCKER ROD, REPLACED WITH 5/8"x36" ROD & CLARE CO, REMONUMENTATION CAP. WE ALSO FOUND THAT ALL THE OLD WITNESSES WERE GONE. FOUND NAIL & TAG (#25861) IN OAK & CHERRY WE USED THE SAME TWO TREES, BUT USED OUR OWN NAIL & TAG. ALSO FOUND NAIL IN RED PINE, WHICH WE USED. ALSO, FOUND FENCE CORNER 33' NORTH OF CORNER AS NOTED IN UNRECORDED SURVEY.

> APPROVED LAND CORNER P.A. 345 of 1990

Clare County Chairman Staul 1.

Date Dec.

This Corner established in Clare County Remonumentation Program.

See dossier for detailed report. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET 5/8" X 36" RE-ROD WITH 3" CLARE COUNTY MONUMENT CAP IN MONUMENT BOX.

WITNESSES: NO* 77.15' - NAIL & TAG IN 36" W. OAK N45°E 67.8' - NAIL & TAG IN 10" R. PINE S45°W 5.3' - NAIL & TAG IN 14" TWIN CHERRY S30°W 47.6' - NAIL & TAG IN 4" MAPLE IN CLUSTER OF 5.

THE OF MICHIO MARK R. ROBISON **PROFESSIONAL** SURVEYOR No. 27458 POFESSION ESSIONA

Marie GC

12-19-94 Date __

Surveyor's Michigan License No. _27458