LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 19 N. ~~S.~~, R. 6 E. ~~W.~~	A-10; A-11; B-11
2. PROPERTY CONTROLLING IN SECTION	,T. N. ~~S.~~, R. E. ~~W.~~	
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 2/25;1/31;2/6, 19 85, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. CONTINUED

A. Description of original monument and accessories and/or subsequent restoration:

B-11

Fd 1¼" well screen on W side old 20" ash stp;
added DNR Mon & ced post w/loc tag

24"	Maple	N15°W	39.00'
6"	Cedar	N30°E	74.07'
28"	W Pine	N80°E	107.18'
26"	W Pine	S70°W	82.55'
Sly edge creek		Due N	330' ± 4'
Ely edge creek		Due W	220' ± 4'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

A-10 - Fd and accepted angle iron for W¼ cor of Sec. 30. Fits cor record data as recorded at Osceola County Register of Deeds. Corner falls in southerly wheel track of E-W winding trail road.

A-11 - Fd and accepted Osceola Co. Monument for SW cor of Sec 30, McClung fd tile here.

B-11 - Fd and accepted well screen by RLS, M. McClung for S¼ cor of S-30. McClung restored Francis Coleman's 1856 resurvey corner per calls to spring & stream to east, top of bluff and sec. corner to west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-10

Fd 1½" x 1½" x 3/16" angle iron;
added DNR Mon.

18"	B Oak	Due E	49.98'
25"	B Oak	S25°E	48.17'
18"	B Oak	S70°W	28.35'
14"	R. Pine	N70°E	13.73'
Set ced post w/loc tag		Due N	33'

A-11

Fd Osceola Co. Mon; added ced post

14"	W Pine	N50°W	9.28'
13"	R Pine	N80°E	13.26'
14"	J Pine	S10°W	19.96'

SIGNED BY Carl F. Roser 01-06-86 DATE

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

REDDING TWP
CLARE COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

Reproduced by the State of Michigan