LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 19 N. ~~S.~~, R. 6 E. ~~W.~~	E-12; F-12; F-13; G-12
2. PROPERTY CONTROLLING IN SECTION	,T. N. ~~S.~~, R. E. ~~W.~~	
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on February 6, 1985, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. CONTINUED:

~~A. Description of original corner rock accessories and/or subsequent restoration~~

F-13

Fd 3/4" x 27" sucker rod w/connector; added RLS cap

Power Pole	N55°W	98.28'
16" W. Pine	N85°E	348.00'
ctr E-W gr rd set ced post w/loc tag	Due N	9'
	Due N	33'
old W-W fn N'ly	East	10'±

G-12

Fd 3/4" iron rod w/RLS cap

3" Balsam	N75°E	27.12'
Power Pole	N85°E	36.23'
20" W. Pine	S25°E	190.66'
ctr gr rd set ced post w/loc tag	Due W	6'
	Due W	33'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

E-12 - Fd and accepted ¼" x 3" Ir. for W¼ cor of Sec. 33 (possible piece of wagon wheel).
F-12 - Estab. ctr of Sec. 33 at intersection of ¼ lines.
F-13 - Fd and accepted sucker rod for S¼ cor of Sec. 33. Corner is in E-W rd. through cattail-willow swp; not much available for Wits.
G-12 - Fd and accepted 3/4" Ir. by RLS, M. McClung for E¼ cor of S-33. Old E-W fn remains to E & W are 2'± N.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-12

Fd ¼" x 3" x 22" iron; added DNR Mon & ced post

4" Maple	N10°E	9.8'
6" Maple	N50°E	27.3'
7" Oak	S45°E	11.3'
6" Oak	S35°W	5.6'

F-12

Drove 5/8" x 34" rerod w/RLS cap & set cedar post w/loc tag

3" Oak	N40°E	40.4'
24" Swp Oak	S05°W	16.4'
2" W. Pine	S75°W	16.4'
4" B. Oak	N35°W	21.2'
Old N-S fn	Due W	3'

SIGNED BY Carl F. Roser 01-06-86 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN CARL F. ROSER (SEAL) LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

REDDING TWP.
CLARE COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET