LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF–:	LOCATED IN–:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 19 N. S., R. 6 E. W.	A-5; B-5;
2. PROPERTY CONTROLLING IN SECTION 7	,T. 19 N. S., R. 6 E. W.	15
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on February 6, 19 85, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. Continued:

B-5

Fd ½" iron rod w/metal cap in monument box

Power Pole	N5°W	89.21'
9" Red Pine	N55°W	170.60'
Ctr dirt road S'ly	Due W	11'
Set cedar post w/loc tag	Due N	66'
Ctr M-61	Due S	8'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

A-5 - 1/2" rod in M.S.H.D. monument box in center of M-61 (E&W).

15 - Established SE corner of SW¼ of SW¼ of Section 7 per standard B.L.M. instructions.

B-5 - 1/2" iron in M.S.H.D. monument box in M-61.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-5

Fd ½" iron rod w/metal cap in monument box

10" Red Pine	N5°E	189.6'
14" Red Pine	N55°E	175.2'
Set Cedar Post w/loc tag	Due N	50.0'
Ctr. trail S'ly	West	6.'±

15

Drove 5/8" x 18" re-rod w/RLS cap

8" Red Pine	N50°W	125.9'
14" Black Oak	N25°W	72.8"
Ctr 6"x6"x3' tall metal Bell Tel Box	S35°W	95.3'
Ctr M-61	Due S	7'
Set cedar post w/loc tag	Due N	68'

SIGNED BY Carl F. Roser 01-06-86 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

(SEAL) STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

REDDING TWP
CLARE COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

Reproduced by the State of Michigan