## LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER	CODE NUMBER	
1. PUBLIC LAND SURVEY	T. <u>19</u> %., R. 6	×.	C-13;	
2. PROPERTY CONTROLL-	31 ,T. 19 \$.; R. 6	*. 7 - W		
3. MISCELLANEOUS PROPERTY IN SECTION	,T N	E. W.		
4. LOT NO, RE	CORDED PLAT			
5. PRIVATE CLAIMS				REGISTER OF DEEDS STAMP AND
I,				
жжаны жана барынын жана жана жана жана жана жана жана	шиниктик колжинекого	как <mark>имими</mark> киям	steretions.	
9" maple Du 11" Ash S4	0°E 13.8' e E 25.3'			
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  C-12- Fd & accepted '2" rerod by RLS, Paul Lapham for '4 cor to secs 31 & 32. This is a restoration of Coleman's 1856 GLO dependent resurvey who reestablished old (original) qtr sec corner. Fd old fn intersection (fn remains N & E) 126'+ S & 18'+ W. A Schaaf position from his Wit. stump remains (no cor evident) is \$27000'E, 20.2'. No evidence of McClung conc. mon.  C-13 - Fd & accepted '2" pipe by RLS, Matt McClung for SE cor of Sec. 31.  7 - Estab. N 1/8 cor on E line S-31 per std B.L.M. instructions.				
•				
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  C-13				
Fd ½" x 18" rerod w/RI DNR Mon & ced post		ced post		
SW cor hse N15°W	31.61	11" Manla	n50°w	30.0'
SE cor Hse N45°E	44.81	15" Maple	N25°E	15.2'
10" Maple N85°E	13.52'	11" ced stp	N65°E	15.0'
SE cor Hse N45°E 10" Maple N85°E 6" Maple S25°W 8" Maple S55°W	02.937 50 131	16" Maple	S70°W	37.8'
	20.13			of Miore
	^			WHITE COOLS TO SE
0 15	()	a. 6.		CARL 2
SIGNED BY Carl 7.	Hour of	6-86	DATE	F. ROSER
SURVEYOR'S MICHIGAN REGISTRATION NO. 12028 SURVEYOR 12028				
FOR STATE AND UNITED STATES AGENCIES:				
SIGNED BY	CHIEF OF BURVEY PARTY		DATE	
APPROVED AND SIGNED BYDATE				
	MICHIGAN REGISTER	EO LAND SURVEYOR		(SEAL)
REDDING TWP.				
SURVEYOR'S MICHIGAN RE	GISTRATION NO		CLA	ARE COUNTY