LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. 19 N. ~~S.~~, R. 6 E. ~~W.~~	G-13;
2. PROPERTY CONTROLLING IN SECTION 33	,T. 19 N. ~~S.~~, R. 6 E. ~~W.~~	10; 12
3. MISCELLANEOUS PROPERTY IN SECTION _____	,T. _____ N. S., R. _____ E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on February 6, 1985, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. CONTINUED:

~~A. Description of original monument and accessories and/or subsequent restoration~~

12

Set 1" x 5' pipe w/RLS cap & ced post w/loc tag

9" W Pine	N30°W	52.8'
12" W. Pine	Due N	115.4'
4" W. Pine	S75°E	65.8'
Old fn cor, N-S-E	S10°E	35'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

G-13 - Fd and accepted 2" pipe, buried 3" in road intersection, for SE cor of Sec. 33. Corner is in approx ctr of E-W gravel road. Ctr of N-S gr-vel road is west, 4'±.

10 - Estab. SW cor of N½ of SW¼ of S-33 per std. B.L.M. instructions. Irregular E-W fn remains to west are 2'± north.

12 - Estab. SE cor of N½ of SW¼ of S-33 per Std B.L.M. instructions. Old N-S fn remains in marsh are East 6'±.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-13

Fd 2" pipe, buried 3".

Power Pole	N50°W	107.55'
Power Pole	N25°E	60.62'
Cor fn post	S50°W	44.05'

10

set 5/8" x 34" rerod w/RLS cap

4" R. oak	N50°W	27.3'
6" B. oak	S50°E	25.0'
3" R. oak	S55°W	37.4'
ctr N-S dirt rd.	Due W	6'
old fn cor W&S	N85°W	37'
set ced post w/ loc tag	Due E	33'

SIGNED BY Carl F. Roser 01-06-86 DATE _____

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

REDDING TWP.
CLARE COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET