LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF–:	LOCATED IN–:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. _____ N. S., R. _____ E. W.	
2. PROPERTY CONTROLLING IN SECTION 16	T. 19 N. S., R. 6 E. W.	4; 8; 12
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. S., R. _____ E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on February 8, 1985, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. Continued:

x ~~A. Description of original monument and accessories and re-monument restoration~~

12
Fd ½" iron rod w/RLS cap in 2" pipe;
added cedar post w/loc tag

9" Maple	N45°W	14.43'
5" Maple	N60°E	12.04'
22" Maple	S25°W	16.46'
Ctr 10' wide creek		
C-NE'y	Due N	248'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

4 - Found & accepted 1/2" rod by RLS, J. Sedgman for ctr. of NW¼ of Sec. 16.

8 - Found & accepted 2" pipe in conc. with RLS cap, J. Sedgman, for SE cor. of SW¼ of NW¼ of Section 16.

12 - Found & accepted 1/2" iron by RLS, John Sedgman, for S 1/8 corner on N-S 1/4 line, Section 16 (SW Cor. of Govt Lot 9).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

4
Fd ½" re-rod w/RLS cap added
cedar post w/loc tag

10" Red Pine	N60°W	10.58'
7" Black Oak	S25°E	28.19'
11" Red Pine	S55°W	15.17'
Ctr trail rd NE&SW	Due N	68'

8
Fd RLS cap in 2" pipe in 6" diam
conc; added ced post w/loc tag

9" Black Oak	N50°W	8.02'
9" Black Oak	S50°E	18.87'
6" Red Pine	S35°W	6.85'
Ctr Creek	Due N	190'

SIGNED BY Carl F. Roser 01-06-86 DATE _____

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

REDDING TWP
CLARE COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

Reproduced by the State of Michigan