SURVEY & REMONUMENTATION

JAN 2 3 2001

SECTION

Signed by

Surveyor's Michigan License No. 27458

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Clare County Remonumentation

	,	in County Indiana	2000	00003278	
For Corners in			CLARI	d for Record in E COUNTY MICHIGAN	
Clare			CHRU	L MCAULAY 1-14-2000 At 11:04 a	m _
(County)	Located In:	Corner Code#:	LAND OR L	CURNER 9.00	- 204
1. Public Land Survey	T. <u>18N</u> R. <u>4V</u>	<u> H-1</u>	2000000		
	T. <u>19N</u> R. <u>4V</u>		! PO BOX	LAPHAM & ASSOC INC 33	
	T R		i	MI 48617	
	TR		#4	109-00	
in Section S. 3. Miscellaneous S.	TR		T	nstrument Lib	er Page
	=="			0000009278 OR	2 20
4. Lot No,			Register	of Deeds Stamp & File Nu	ımber
5. Private Claims			1 Tables	01 - 00 m 0 0 0 0 0 1 1 0 1 1 0	
			-		
			4.00.0		
I, Mark R. Robison, in a field survey P.A. 74, Michigan P.A. of 1970, the			IA B C	DEF'GHIJKLM	
conformance with regulations and ru	les therefore as required in t	he current manual of survey	2 6	5 4 3 2 1 1	
instructions of the United States Dep decree of a Court of Law and/or that			4 7	8 9 10 11 12	
conformance with the rules of the M	ichigan Board of Land Surve	eyors or by a Decree of a Court of	5	~~ ·~ · · - · · - · ·	
Law, established, re-established, morbelow.	numented, re-monumented, i	recovered, found as expressed	6-18-	17 16 15 14 13	
DCIOW.			8-19	20 21 22 23 24	
NOTE: Not more than 2 cor	ners, all in the same t	own and range, may be	9-1-	·	
recorded on this certificate.	, , , , , , , , , , , , , , , , , , , ,	- · · · · · · · · · · · · · · · · · · ·	10-302	71 75 51 51 51 65	
	÷;		12-31	32 + 33 + 34 35 + 36	
This is a single corner com	mon to TI8N, R4W,	& T19N, R4W.	13 11.1.1.		
A. Description of original restoration:	monument and acces	sories and/or subsequent			
	,				
GLO	v.43			1	
Nicholson, 1838	· [1]			· P	
B. Oak 22" N2°W, 50 LINKS B. Oak 8" N66°W, 54 LINKS	i ii			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
D. Ouk o 1100 W, 54 LINKS	• • • • • • • • • • • • • • • • • • •	Survey, Lapham, 1977, L2	Po 218	Survey, Robison, 1996, L62	1 Po 356
MDSH, card, Slattery 1958		Same as LCRC #312-77		Same as LCRC #312-77	.1.18.550
1/2" pipe in concrete by Moor	re			•	
4" Oak N70°E, 6.38		Survey, Sedgman, 1978, L	2. Pg. 359	APPROVED LAND COR	HER
5" Birch N89°E, 17.45 4" Maple S30°E, 6.95		Same as LCRC #312-77 H-13 to 1-13 = 2634.74		P.A. 345 of 1990	
· Maple 550 E, 6.75		11-13 to 1-13 2034.74		Clare County	/
LCRC, Lapham, 1977, #312-		Survey, Robison, 1994, L3	3. Pg. 448	Chairman And Adh	e
Found concrete monument, sa	me 3 witnesses	Same as LCRC #312-77		Date 8-30-00	-
as MDSH card	e 1			3	
B. Description of corner evide	ence found and/or meth	od applied in restoring or re	e-establishing co	rner.	•
			•		
No GLO evidence found. For	and concrete monumen	t and remains of maple stun	ap of 1958 witne	ess SE. Measured distance H-	13 to I-13 as
2634.74. Accepted found cor	icrete monument as bes	st available evidence of acce	pted position of	the corner.	
C. Description of monument	for corner and accessor	ies established to nemetuate	locating the nos	sition of the corner	
•		to perpendice	roouting me pos	man or the corner.	
Set 5/8" x 36" rerod with Clar	e County Remon Cap i	narked P.S. #27458.		THE OF MICH	
Witnesses:	1 v 100 D ad Oak			Par Carl	
N66°W, 16.75' - N & T in 14' N84°E, 33.33' - N & T in 18"				MARK R. ** ROBISON **	\
N35°E, 34.17' - N & T in 11"				PROFESSIONAL E	}
N3°E, 34.00' - N & T in 7" R			Ę.	M SURVEYOR	}
			1	No.	
				27458 6	
	00:			OFESSION TO	
m. W.	DD:	4		CONTRACTOR OF THE PARTY OF THE	

1-13-2000

Date