## SURVEY & REMONIMENTATION CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MAR 24 2000

## **Clare County Remonumentation**

titur o T		ire County Remonant	
For Corners in ECTIC	)N	ı	199900009793 Filed for Record in CLARE COUNTY MICHIGAN CAROL MCAULAY
(County)	Located In:	Corner Code#:	On 11-10-1999 At 01:30 pm. LAND CORNER 9.00
1. Public Land Survey	T. <u>20N</u> R. <u>3W</u> T R T R		OR Liber 2 Page 72 - 72  Instrument Liber Page 199900009793 DR 2 72
<ul><li>2. Public Controlling in Section</li><li>3. Miscellaneous</li></ul>	S T R S T R S T R		#383-99
	S T R , Recorded Plat	and the second s	Register of Deeds Stamp & File Number
5. Private Claims			
I, Mark R. Robison, in a field survey on July 22, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below.			1ABCDEFGHIJKLM 2-6-5-4-3-2-1-3-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
A. Description of original restoration: 1856 Adair 80.47 Set Post Cor Sec. 29-1 W. Pine 30 N55E 20 Hmlk 28 S39W 44		sories and/or subsequent	
1899 Harper, CSR, B-1 Pg. W.P. S. 24" N70W 44 Hemlock 22 N55E 21	1 & B-4 Pg. 1	1975 McClung, (132) 1-921 Found Sec Cor See LCRC for witnesses	1980 Sedgman, (132) 2-597 Fd 1" Pipe S80E 35.02 P.P.
1912 Johnson, CSR 5-138 & N.W. Cor School Hse S50E Meas. North 80.70 to Sec C	132	1972 Courtright, LCRC #41 1 ½" Pipe 2" deep Same witnesses as (132) 1-678	N35E 70.14 P.P. N80E 134.85 24" Oak Meas. South 2676.38 to C-12
1972 Courtright, (132) 1-18 Reference Sec Cor as S.W.		1974 McClung, LCRC #192 Fd 1" Pipe S87E 34.6 P.P	1992 Geers, LCRC #735 Fd & accepted 1" pipe corner falls 8' South of C.L. dirt road West Raised with ½" rebar & cap
1973 Radcliffe, (132) 1-678 Fd ½" Pipe S85E 34.70 P.P. N40W 69.90 P.P. S45E 41.22 Cor Fe Post Meas. East 2733.68 to D-11		N40W 69.8 P.P. N35E 57.7 C.L. of stone	N31W 70.11 P.P. S82E 35.06 P.P. S39E 94.46 S.W. Cor Conc. Post N85W 47.96 Fence Post
See dossier for detailed Fd 1/2" x 18" iron over c	report. abin spike in Mon. Box. Fo		4 witnesses, three 1980 witnesses and three 1992 witnesses
·	·		s S45E 87.00 (CSR 87.1) to N.W. Cor of school house.
		ies established to perpetuate lo ble evidence of the perpetuation	APPROVED LAND CORNER
N72°E 134.71 C.L. 30" C East 95.13 Fd N & T in F S52E 102.54 S.W. Cor C	P.P. (OBT)	MARK R.	P.A. 345 of 1990 Clare County
N88W 38.03 N & T in Co N38W 69.94 N & T in P. Signed by	or. F. Post (OBT)	ROBISON * PROFESSIONAL 5 SURVEYOR &	Chairman <u>Paul 1 · Iophu</u> Date <u>9-15-99</u> Date 11-8-99
Surveyor's Michigan L		No. 27459	RM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN.28, 19
		POFESSIONA	REVISED MAY 14, 191 REVISED JAN., 198