
LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich., PA 1970

4. Lot No:	3. Miscellaneous Property in Section	2. Property Controlling in Section	(County) 1. Public Land Survey	For Corners in: Clare
Recorded Plat:	S	0 0 0 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	⊣ i	
lat:		20N		Located In
	д д 	R 3W	70 	ਹ
		9		Corner Code #

I. <u>Craig W. McVean</u>, in a field survey on <u>Sept. 3</u>, 20<u>03</u> do hereby state that under requirements of PA 74. Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

Private Claims:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



ج <u>۱</u>۵ Description of original monument and accessories and/or subsequent restoration:

None

15 - None

CE 1/16th corner, Section 4. Set 2" Aluminum Cap on 5/8" x 34" rebar per standard BLM procedure. 8' North to Centerline of trail E-W.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

15 - W 1/16th Corner common to Section 4 and Section 9.

9 - CE 1/16th corner, Section 4. Set 2" Aluminum Cap on

Set 2" Aluminum Cap on 5/8" x 34" rebar per standard BLM procedure. No.
39088
SURVEY
SECTION rebar per standard

OBSNBOIT

**

O F

MICHICA TO

<u>ю</u> С

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- 2" Aluminum Cap on 5/8" x 34" rebar.

Set Blue Carsonite Post 1' SW

S63°E 7.60' to set N & T in NE. side 5" White Pine
S11°W 32.69' to set N & T in E. side 15" White Pine
S70°W 17.04' to set N & T in S. side 15" Triple W. Oak
N10°E 45.38' to set N & T in W. side 8" White Pine

S05°W 11.90' to set N & T in E. side 3" Red Maple
S05°W 11.90' to set N & T in E. side 3" Red Maple

Surveyor's Michigan Licerise No.:

Signed by:

39088

Date: