## REMONUMENTATION!

JAN 2 3 2001

SECTION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 **Clare County Remonumentation**

| (County)              | Located In:     |       | Corner Code# |     |
|-----------------------|-----------------|-------|--------------|-----|
| 1. Public Land Survey |                 | T. 20 | N R. 5W      | K-9 |
|                       |                 | Т     | R            |     |
|                       |                 | Т     | R            |     |
| 2. Public Controlling | S               | _ T   | R            |     |
| in Section            | S               | _ T   | R            |     |
| 3. Miscellaneous      | S               | _ T   | R            |     |
| Property in Section   | S               | T     | R            |     |
| 4. Lot No             | , Recorded Plat |       |              |     |
| 5. Private Claims     |                 |       |              |     |

200000010161
Filed for Record in CLARE COUNTY MICHIGAN CAROL MCAULAY -2000 At 07:44 am. JER \_ 9.00 LAND CORNER OR Liber 2 Page 284

Instrument Liber Page 200000010161 OR 2 284

x489-00

Register of Deeds Stamp & File Number

I, Mark R. Robison, in a field survey on November 9, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1ABCDEFGHIJKLM 2 7 8 9 10 5. 18 17 16 15 8 19 21 24 20 22 23 i 9 10 30 27 29 28 26 25 11 12 31 33 34 35 36

A. Description of original monument and accessories and/or subsequent restoration:

GLO, Adair, 1856

Set Post

Y. Pine 22" N52°W, 29 LINKS

Y. Pine 24" S60°E, 48 1/2LINKS

CSR, Johnson, 1935 Bk 2. Pg. 64 & 65

No Witnesses

K-9 to I-9, 79.80 chains

K-9 to M-9, 81.67 chains

LCRC, Lapham, 1977 LCRC #314-77

Fd 1" pipe at int. Rds. N-S-E

Three witnesses

LCRC, Roser, 1992 LCRC #717-92

Fd 1/2" rod in Mon. Box at int. Black-top

road N-S and gravel road East. Four witnesses and cedar post.

Survey, Roser, 1994, Unrecorded Same as LCRC #717-92

K-9 to I-9, 5264.58 K-9 to M-9, 5396.88 K-9 to L-9, 2684.49

APPROVED LAND CORNER

P.A. 345 of 1990

Clare County

Date 12-13-00

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner.

Found 1/2" rod in Mon. Box in asphalt pvm't. Verified two 1977 witnesses (stumps) and three 1992 witnesses (one was stump). Verified DNR distances to I-9, L-9, and M-9 by G.P.S. Accepted 1/2" rod as best available evidence of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 36" rerod with Clare County Remon Cap marked P.S #27458 in Mon. Box.

Witnesses:

N49°E, 89.00' - N & T in 10" Oak

S40°E, 79.05' - N & T in 10" J. Pine

N38°E, 90.95' - N & T in 10" x 12" Twin R. Oak

S85°W, 50.83' - N & T in 3" W. Pine

Surveyor's Michigan License No.

力力 MARK R. **ROBISON** STORNOCK A PROFESSIONAL SURVEYOR Mr.

Creasion,

SESSION PRO

, M APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN.28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983