35

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 Clare County Remonumentation

Clare (County)		Located In:	Corner Code#:	CLAI CARI Dn (
1. Public Land Survey	,	T. <u>20N</u> R. <u>5W</u>	A-5	ÜRÜ
		T. <u>20N</u> R. <u>6W</u>	<u>M-5</u>	
	•	T R		
2. Public Controlling	S	T R		19
in Section	S	T R		
3. Miscellaneous	S	T R		
Property in Section	S′	T R		
4. Lot No	, Recor	ded Plat		Register
5. Private Claims				•

I, Mark R. Robison, in a field survey on August 25, 1999, do hereby certify that under requirement of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

This is a single corner common to T20N, R5W, A-5 and T20N, R6W, M-5

A. Description of original monument and accessories and/or subsequent restoration:

1856 Adair Old Post for Corner S. Pine 6 N17 ½ W 18 Lks. S. Pine 9 S36W 17 Lks.


11-07 Johnson, CSR BK-4, P. 137 M-5 to M-4, 40.20

8-33 Johnson, CSR BK-2, P.51 Oak 10" S52E, 162 Oak 6" N69E, 56 Oak 10" S45-30W, 99 A-5 to C-5, 76.48 ½ 7-76 Ostling LCRC #279
Fd 1 1/4" Pipe at rd, Int. apparently
used in a survey of Sec. 12 by Con. Pow Co.
& possibly others. Also fd another
iron bar about 10' N.W. of undetermined
origin and can find no record. Does not
fit C.P.C. Survey of Sec 12. Set DNR Mon.
in place of pipe. S77W 47.50 6" Oak
N66W 69.00 7" Oak
N10W 10.37 1" Iron Bar

199900007871 Filed for Record in CLARE COUNTY MICHIGAN CAROL MCAULAY On 09-20-1999 At 11:15 am. LAND CORNER 9.00 OR Liber 2 Page 35 - 35

Instrument Liber Page 199900007871 DR 2 35

Register of Deeds Stamp & File Number



P.A. 345 of 1990 Clare/County

Chairman Alauld;
Deta 9-15-44

5-92 Roser LCRC #688 & DNR Plan R-18-AB Fd 1" pipe (DNR Alum Cap Gone) for S.W. Cor Sec. 7 K. Osling fd 1" pipe here in 1976 Dept. Sur. that fits Cons. Power Co. Survey of Sec. 12 (T20N, R6W). Also fd another iron N10°W, 10,4 ft. that K. Ostling fd but could not find record of & did not fit Cons. Power Co. Survey. So KJO did not accept. Raised with 7" Galv. Pipe W/RLS Cap. N67W 69.42 16" B. Oak N55E 60.18 7" B. Oak S30E 84,79 3" J. Pine \$35W 100.60 8" B. Oak

Meas, E 2403.57' to B-5

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

See dossier for detailed report.

Found I" x 7" pipe over DNR pipe (cap removed). Fd two 1976 witnesses, two 1990 witnesses and I" iron N10°W 10.4' per Roser LC' Fd DNR Wit. Post 33' West.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Accepted DNR pipe and raised with 5/8" x 8" rerod with std Clare Co. Remon Cap marked P.S. #27458. Accepted as best available ev of the accepted position of the corner.

Witnesses:

N62°W 69.47 Fd N & T in 20" B.Oak (OBT) N33°E 80.12 Set N & T in 8" J. Pine N54°E 48.68 Top Cen. Tele. Riser S72°E 111.05 Cen. 3" Pipe (Gas Line Marker)

Signed by MARCH (2/63/50)

Signed by Surveyor's Michigan License No. 27458



OPESSION

Date 9-15-99

M APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS,