

Subsequent recordation of this corner by Ronrle M. Lester, PS 18998 and recorded in L.1, P.607 dated 12/26/72 stating he f
the corner as called for by MDOT

- Set nail & tag West side corner post, North, 8.18'
- Found nail & tag South side 24" willow, ENE, 81.65'
- Found nail & tag West side 16" cherry, SE, 66.76'
- Found nail & tag West side 12" oak, SSE, 51.00'

Unrecorded survey by Marvin F. Fouty, PS 18989 of Kyes Engineering & Associates, Inc., dated 6/24/76

- | | | |
|---------------------------------|-----|--------|
| Pipe | | |
| nail & tag in W side cor. post | N | 8.18' |
| nail & tag in S side 24" Willow | ENE | 81.65' |
| nail & tag in W side 18" Cherry | SE | 66.76' |

Unrecorded survey by Larry A. Bryan, PS 25832 of Bryan Land Surveys, PC, dated 6/30/87

- | | | |
|--|---------|--------|
| 3/4" Pinch Pipe in fences East, West and North | | |
| Found 4" clay pipe (NW cor. Sec.3, T4N, R1W) | East | 25.70' |
| Found nail & tag #18998 W. side post | North | 8.18' |
| Centerline 15" Oak | S 10° E | 51.0' |