FEB 0 2 1998

SECTION

5. Private Claims

REMONUMENTATION **OLIVE AND DEWITT TOWNSHIP** LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

LIDER 004 PAGE 202 RECORDED

For corners in			
Clinton (County)	Located in:	Corner Code #	Oct 17 9 17 AM '97
Public Land Survey	T_6NR_2W T_5NR_2W	J-13 	REGISTER OF DEEDS OLINTOR CHUNTY, MICH. Canal Woolly
Property Controlling In Section	STR STR		
Miscellaneous Property in Sec.	STR STR		Register of Deeds Stamp & File Number
4 Lot No	Recorded Plat		A B C D E F G H I J K L

1, Mark L. VanRaemdonck, in a filed survey on August 21, 1997, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this

- A. Description of original monument and accessories and/or subsequent restoration:
 - 1. Original Lucius Lyons 1826 Mon: Wood Post

Access: B. Oak 14 N76°E 77

W Oak 18 N79°W 76

2. County Surveyor Hollister Field Book 2, P. 157 Aug. 19-1899

Mon: Stone with stake below Access: Cherry 10 N48°W 40 Hickory 15 N14°W 127 1/2

(continued on reversed side of this sheet)

Ĵ d

S

8

7

ล

9

10

12 រោ

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found 3/4" pipe with cap #20708 as referenced in No. 3 and 4 above. I accepted this location as the original corner position based on the best available evidence. Based on historical evidence and measurement capabilities of early surveyors. This corner has been used extensively in establishing boundaries in the area and to do otherwise would be disruptive to the area.

C. Description of monument for corner and accessories to perpetuate locating the position of the corner

Removed 3/4* pipe and replaced it with a STD Clinton County Remonumentation Monument. The monument is wilnessed by the following accessories:

Found P. K. & tag #39100 in W. side 24" Hickoory M.D.O.T. reference tag in E. Face Util. Pole 5.12 18.17 NO5E N05W

Centerline asphalt pavement Round Lake Road 46.60 North

SECE 42.08

NW cor. house foundation Set Nail & Tag #24622 in N, face 10" Spruce SBOE 74.78 N89"43"15"W 2622.48' STD Clinton County Mon at I-13, T6N-R2W \$89°41'17"E 2639.98' STD Clinton County Mon at K-13, T6N-R2W

Date <u>SEPT. 8, 1997</u>

Surveyor's Michigan License No. 24622

Signed by

MARK L. MARK L.
VANRAEMDONCK * VANRAEMDONCK * PROFESSIONAL SURVEYOR OF No. 24622 No. 24622 PARTIES OF ESSIONAL MINIMUM MINIMUM

FORM APPROVED BY MICHIGAN STATE BOARD OF LAID SURVEYORS REVISED MAY 14 11 REVISED JAN 11

> APPROVED BY CLINTON COUNTY PEER GROUP

A. Description of original monument and accessories and/or subsequent restoration:

(continued from front)

Edwin Morse L.C.R.C. L. 2, P. 313 April 1980
 Mon: 3/4" X 30" pipe with R.L.S. Cap #20708
 Access: N40°E 42.50' M.D.S.H. ref. tag in 30" box elder

North 18.50 M.D.S.H. ref. tag in tele. pole

S35°E 49.41' NW cor. of conc. patio S60°E 42.13' NW cor. house foundation N55°E 19.95' P.K. nail in conc. driveway

4. Kay Don Fluke, L.C.R.C. L. 2, P. 407 10/6/81

Mon: Found 3/4" X 30" pipe with R.L.S. cap #20708 (Rec. as J-1 T5N-R2W)

Access: N40°E 42.50° M.D.S.H. ref. tag in 30" box elder

North 18.50° M.D.S.H. ref. tag in tele, pole

\$35°E 49.41° NW cor. of conc. patio

\$60°E 42.13° NW cor. house foundation

\$85°E 19.95° P.K. nail in conc. driveway

(Mr. Fluke declares corners J-1 T5N-R2W and J-13 T6N- R2W are common).

LIDER 004 PAGE 203