CLINTON COUNTY REMONUMENTATION

EAST 1/2 CORNER SECTION 13, T5N, R2W, DEWITT TOWNSHIP, CLINTON COUNTY, MICHIGAN

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 004 PAGE 292

For corners in					RECO	Buci	`								
CLINTON Located In: Corner Code #				1	11600	TYD C. (,								
1. Public Land Survey 2. Property Controlling in Section 3. Miscellaneous Property in Sec.	County T SN R 2W M-6 T R T T						DEC 28 3 39 PM '98 REGISTER OF DEEDS CLINTO TO CHITTI MICH. Canada Workley Register of Deeds Stamp & File Number								
		· <u></u>					· ···-								
4. Lot No, Re 5. Private Claims	corded Plat			A B	C D	E F	G H	IJK	L M						
	4			6	5	4	3	2	1 .						
I, Arden S. Pierson, PS , in a field survey on SEPTEMBER 17 19 98 , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points				7	8	9	10	11	12						
as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a degree of a Court of Law and/or that the					17	16	15	14	13						
corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:				19	20	21	22	23	24						
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.			9 10 11	30	29	28	27	26	25						
A. Description of original monument and accessories and/or subsequent restoration: TOWNSHIP BOUNDARY SURVEY BY LUCIUS LYON IN 1826.				31	32	33	34	35	36						
ON EAST BOU 40.00 SET H	NDARY OF SECTION 13.	Y - S17°W - 13 (I.TMKS)	(8.58′))											
CERTIFIED S PAGE 742,G	URVEY BY FRED WHITE, IVES NO TIE TO CORNE	PS #12034, DATED 11/20,	'97, REC	CORDE	D IN	LIBE	ER 78:	3,							

- Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND NO PHYSICAL EVIDENCE OF CORNER MONUMENTATION. SET NAIL ON TOWNSHIP LINE MIDWAY BETWEEN SECTION CORNERS, ACCEPTED AS A CAREFUL AND FAITHFUL RE-ESTABLISHMENT OF THE POSITION OF THE ORIGINAL CORNER.

REMOVED NAIL AND SET STANDARD CLINTON COUNTY MONUMENT AND MONUMENT BOX.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

EAST % CORNER OF SECTION 13, T5N, R2W.

STANDARD CLINTON COUNTY MONUMENT IN MONUMENT BOX.

WITNESSES

NAIL & TAG #13039 IN NE SIDE POWER POLE - S33°E - 105.16' NAIL & TAG #13039 IN NE SIDE POWER POLE - S18°E - 105.86'
NAIL & TAG #13039 IN SE SIDE CUT UTILITY POLE - S43°W - 31.22' SW CORNER TELEPHONE PEDESTAL - S67°E - 45.84'

FROM SOLAR OBSERVATIONS N00°06'36"W 2639.71' - M-5, DEWITT TOWNSHIP S00°13'53"E 49.75' - A-6, BATH TOWNSHIP

ARDEN S.
PIERSON
PROFESSIONAL
SURVEYOR
No.
13039 13a. *STANDARD CLINTON COUNTY MONUMENT IS A 21/" DIAMETER STEEL TUBE 30" LONG WITH A STAMPED BRASS CAP AND A BREAKAWAY MAGNETIC BASE.

APEROVER BY CUNTON COURSE PRER GROUP

Signed by Olda S. Pely			ñ/a Ch	3/23/98 A703	nn 1,
Signed by Man Signed by	Date _	SEPTEMBER 21,	1998		
Surveyor's Michigan License No. 12020					