SUMMEYE I WENT TON

FEB 2 2 1998

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION

For corners in		,		KECOKDED		
	Clinton	Located In:	Corner Code ≠			
	(County)			Mar IC . O . Du to t		
1.	Public Land Survey	T 5N R 2W	A-9, A-13	HAR 15 3 37 PH 194		
		Τ R τ <u>5Ν</u> R <u>3 W</u>	M-13	REGISTER OF DEEDS CLINTON COUNTY, HICH.		
		TR		Carols Woolege		
2,	Property Controlling	S T R		<i>(</i> /		
	in Section	S T R		LIBER 4, PAGE 16		
3.	Miscellaneous	S T,R		Register of Deeds Stamp & File Number		
	Property in Sec.	\$ T R				
4.	Lot No	, Recorded Plat		ABCDEFGHIJKL		
5.	Private Claims					
				3		
				3) <u> </u>		

I, Arden S. Pierson P. Sn a field survey on October 21 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
 - A-9 Original survey by Harvey Parke, D.S., in 1827, Chas E. Hollister, County Surveyor Records stone, with iron below June, 1880 - Recorded Corner in Liber 1, page 131. - Recorded by F. White P.S. in Liber 1, page 393.
 - A-13 Original survey by Harvey Parke D.S., in 1827, recorded in Liber 2, page 598 - MDOT survey notes record survey information for SE ¼ Section 36, T5N, R3W.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Dewitt Township

- A-9 (SW corner-Section 19) Found 3" rod in monument box @ South edge of pavement -East- Accepted monumentation and placed Standard Clinton County Monument in existing monument box.
- A-13 (SW corner-Section 31) Found boatspike in monument box Verified with MDOT reference point - Excavated below and found boatspike buried 24"- Placed Standard Clinton County Monument and replaced monument box
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-9 (SW corner-Section 19) (Standard Clinton County Monument in monument box)

A-13 (SW corner-Section 31) (Standard Clinton County Monument in monument box)

Watertown Twp. corner -North- 13.20'	Boatspike -North- 77.06'			
N & T SW side power pole -N22°W- 107.73'	PK nail S. side telephone pole -N80°W- 31.70'			
If the place evalue bose was a server	N & T #16053 NW side telephone pole -N64°E- 52.83'			
N & T #25832 SE side cut off utility pole -N24°E- 102.11'	N & T #16053 W. side power pole -S12°E- 85.20'			

N & T #25832 SW side light pole -\$35°E- 46.33' N & T E. side power & telephone pole -S16°W- 154.95',

**Standard Clinton stamped brass ca	County Monument	is a 2" steel tube, 30" long	te November 24, 1993	E// 6/30
	13039	CLINTON COUNTY PEER GROUI	P FORM APPROVED BY MICHIGAN STATE BUMB OF LAND SHARE	31
Surveyor's Michigan License No.	1000	DATED 12/8/93	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SHAPE	graðs, jan. 26. 15 Evised may 11. 19 Ylandern mus á